



CPX Software Release Notes GW1032/1042 Series

Release CPX-25.04.57.000

Hardware Models	GW1032; GW1042 Series
Revision	1.00.22
Approval status	Approved
Date:	03 April 2025
Brief description	Details the release of system software CPX-25.04.57.000 for GW1032/1042 Series



1		Revi	sion history	.3
2		Rele	ase statement	.3
	2.	.1	Firmware information	. 3
	2.	.2	Hardware platforms	. 3
			Important upgrade information	
3		Secu	ırity fixes	.4
4		Secu	ırity vulnerabilities	.6
5		New	features	.6
6		Dep	recated features	.8
7		Knov	wn issues	.8
8		Prob	olems resolved	.9
9		App	endix 1: New features history	12
	9.		Release 25.04.35.000	
	9.	.2	Release 25.04.19.000	13
	9.	.3	Release 25.03.43.011	17
	9.		Release 25.03.43.005	
	9.		Release 25.03.43.000	
	9.		Release 25.03.03.000	
	9.		Release 25.02.14.033	
	9.		Release 25.02.14.027	
	9.	.9	Release 25.02.14.016	
	9.	.10	Release 25.02.14.010	19
	9.	.11	Release 25.01.40.028	22
1	0	App	endix 2: Problems resolved history	
	1(0.1	Release 25.04.35.000	
		0.2	Release 25.04.19.000	
	1(0.3	Release 25.03.43.011	
	1(0.4	Release 25.03.43.005	28
	1(0.5	Release 25.03.43.000	
		0.6	Release 25.03.03.000	
	1(0.7	Release 25.02.14.033	
		8.0	Release 25.02.14.027	
		0.9	Release 25.02.14.016	
	1(0.10	Release 25.02.14.010	
	10	0.11	Release 25.01.40.028	39



1 Revision history

Date	Revision	Description
02 November 2016	1.00.01	Release notes for CPX-19.00.02.000
15 May 2017	1.00.02	Release notes for CPX-19.00.04.000
20 October 2017	1.00.03	Release notes for CPX-19.00.75.000 RC 15 (limited)
24 November 2017	1.00.04	Release notes for CPX-19.00.75.000
19 January 2018	1.00.05	Release notes for CPX-19.00.75.001
09 April 2018	1.00.06	Release notes for CPX-19.00.77.000
09 August 2018	1.00.07	Release notes for CPX-19.00.78.000
20 February 2019	1.00.08	Release notes for CPX-19.00.80.000
07 October 2019	1.00.09	Release notes for CPX-19.00.86.000
18 May 2020	1.00.10	Release notes for CPX-19.00.91.000
05 March 2021	1.00.11	Release notes for CPX-25.01.40.028 (and bridge release CPX-19.01.40.028)
24 February 2022	1.00.12	Release notes for CPX-25.02.14.010
14 April 2022	1.00.13	Release notes for CPX-25.02.14.016
23 June 2022	1.00.14	Release notes for CPX-25.02.14.027
29 July 2022	1.00.15	Release notes for CPX-25.02.14.033
23 February 2023	1.00.16	Release notes for CPX-25.03.03.000
22 May 2023	1.00.17	Release notes for CPX-25.03.43.000
14 August 2023	1.00.18	Release notes for CPX-25.03.43.005
15 November 2023	1.00.19	Release notes for CPX-25.03.43.011
26 September 2024	1.00.20	Release notes for CPX-25.04.19.000
18 November 2024	1.00.21	Release notes for CPX-25.04.35.000
03 April 2025	1.00.22	Release notes for CPX-25.04.57.000

2 Release statement

CPX-25.04.57.000 has formally passed internal acceptance and regression testing and is available for general release on hardware platforms as stated below.

2.1 Firmware information

Filename	Size (bytes)	Build Date	Checksum (md5)
CPX-25.04.57.000.image	11,988,992	03/4/2025	0b932b883933dc987afb1de8816ee502

2.2 Hardware platforms



GW1032	Dual SIM 3G/CDMA450 wireless router with dual Ethernet and WiFi.
GW1042	Dual SIM LTE/3G/CDMA450 wireless router with dual Ethernet and WiFi.

2.3 Important upgrade information

Due to a unified versioning schema across all software families CPX firmware recently changed its MAJOR version number (previously **19**, now **25**).

Older firmware contains safety checks to ensure that the MAJOR firmware version matches before allowing firmware upgrade. More recent CPX firmware relaxes this check to allow seamless upgrade from CPX-19 to CPX-25 versions.

In order to accommodate this change, release CPX-25.01.40.028 is accompanied by a corresponding 'gateway' release CPX-19.01.40.028 (functionally identical to CPX-25.01.40.028).

Please follow the steps below for upgrade:

Running firmware	Upgrade procedure
< CPX-19.00.91.000	Upgrade to CPX-19.01.40.028 before to upgrade to CPX-25.01.40.028 or later
>= CPX-19.00.91.000	Upgrade directly to 25.01.40.028 or later

3 Security fixes

Firmware	Module	Description	Severity	Mantis
25.04.57.000	luci	Added Security-Policy-Header (CSP) to prevent clickjacking	Low	8087
25.04.35.000	openVPN Updated to version 2.5.11 Fixes CVE-2022-0547		Irritant	6238
	pam_tacplu s	tacplu Avoid potential freeing of non-address Fixes CVE-2020-27743 and CVE-2016-20014		8002
25.04.19.000	Updated to version 2.90 4.19.000 dnsmasq Fixes CVE-2023-28450 and CVE-2022-0934		Medium	7796
	dropbear	Updated to 2022.85	Medium	7560
frr jquery net-snmpd		Fix CVE-2024-44070. FRRouting (FRR) does not check the actual remaining stream length before taking the TLV value.	Medium	7858
		Updated to version 3.7.1	Medium	7914
		Updated to version 5.9.4	Medium	7306



		Fixes CVE-2022-44793; CVE-2020-15861; CVE-2020-15862; CVE-2019-20892; CVE-2015-8100; CVE-2018-18065; CVE-2018-18066; CVE-2014-2285		
	password	New HMAC password hashing algorithm which uses the HMAC functionality in the TPM as a means of hashing passwords (IEC62443-4-2)	Low	7155
	PPP	Updated to version 2.5.0	Low	4179
	System	Delete sensitive information from RAM and generate syslog message after use by luci, uhttpd, PAM, openVPN and strongswan (IEC62443-4-2)	-	7164 7166 7167
		Perform image digital signature verification in virtual memory prior to loading to flash when using to Web UI and Activator.	Low	6721
	uhttpd	Support TLS v1.3 (IEC62443-4-2).	-	6854
25.03.43.005	console	Automatically log out console sessions after 30 mins if inactivity	Low	6884
25.03.23.000	telnetd	Remove telnetd support	Medium	
	password	Resetting password via web UI now requires input of current password	Low	5261
	SSH	Added grace period after console login failure to disrupt brute force attacks	Medium	5853
25.02.80.000	dnsmasq	Updated to 2.85 to fix CVE-2021-3448	Low	6041
	gpsd	Updated to 3.23.1	-	
	overlay	Implemented automatic overlay clean up to remove ad hoc modifications	-	5374
	snmpd	Application now runs with dedicated unique user and group id instead of root privileges	-	4695
25.02.14.000	arp-scan	Upgraded to version 1.9.7	-	
	iecd	COTP: fixed possible heap buffer overflow when handling message with invalid (zero) value in length field). Fixes CVE-2020-7054	-	5320
	iproute2	Upgrade to version 5.13.0		
	uClibc	Upgrade to version 0.9.33.2	-	
25.01.40.034	chrony	Upgraded to v3.5.1	-	
	dnsmasq	Upgraded to v2.84 to fix vulnerabilities in DNS response validation Fixes CVE-2020-25684; CVE-2020-25686	-	5618
25.01.40.028	chrony	Disable internet command sockets	-	4995



chrony			
dropbear			4964
iecd			4966
iosrvd			4968
openvpn	Applications now run with dedicated unique		4970
rtud	user and group id instead of root privileges		4971
rtuu			4973
strongswan			4974
tservd			5003
xl2tpd			
Password	New configurable option to use SHA-512 for password hashing	-	5001
	Config1 and config2 are now deleted when		
Reset	the router is reset to factory config using the	-	4996
	reset button press		
tservd	TLS support for TCP server and TCP client	_	
t3EI VU	mode	-	

4 Security vulnerabilities

Module	Short Description	Severity	Mantis
bgpd	Vulnerabilities affecting current version of bgpd	Low	5808
	CVE-2016-1245		
dropbear	Allow configuration of strong SSH cryptographic algorithms in dropbear	Low	8359
openssl	Vulnerabilities affecting current version of openssl	Medium	7301
	CVE-2022-1292, CVE-2022-2097, CVE-2022-4304,		
	CVE-2022-4450, CVE-2023-0215, CVE-2023-0286,		
	CVE-2023-0464, CVE-2023-0465, CVE-2023-0466,		
	CVE-2023-2650, CVE-2023-3817, CVE-2023-4807,		
	CVE-2023-5678, CVE-2022-0778, CVE-2022-2068		
pam	It is possible to enumerate users using console log messages	Medium	8366
syslog	Hide sensitive information in change logs	Low	8365

5 New features

Network				
	• •	•	i Path (ECMP) feature. Route has a teway/interface pairs to route over.	
Multi Path	Package	Section	Options	8219
Routes	network	mp_route	paths; target, netmask, metric, mtu, mark	8250
		mpath	interface; gateway, weight	



NTP min/max poll interval	Allow configuration of minpoll and maxpoll interval using existing NTP interval hours option (space separated parameters)					
	Package		Section Options	8318		
	system		timeserver interval_hours			
Password Scramb	oling					
Monitor SNMP	Monitor SNMP v3 password options now added to the set of passwords fields that can be scrambled					
v3 passwords	Package	Section	Options	8090		
	monitor	keepalive	snmp_auth_pass; snmp_priv_pass			
Scada						
Automatic IEC104 point configuration	Support auto	omatic IEC104 p	point configuration after IEC61850 SCL	8248		
DNP3 G10 and	Support conv G41 to IEC6		IP3 Binary Output Command G10 and	8100		
G41	Package	Section	Options	0100		
	iecd	point	iec101_qu			
IEC101 to IEC104 Fully Transparent mode	ASDU CA wh ability to rep	Support IEC104 to IEC101 transparent mode which allows any ASDU CA when ca configured in the link is zero. Also provides ability to replace IEC101 message TypeID with another configured TypeID before it is transmitted to IEC104.				
IEC104 Type ID 51 and 64	Support for IEC104 Slave to IEC104 Master Bitstring command conversion					
	Support VRTU data types and periodic auto updating per point					
VRTU data	Package	Package Section Options				
types	iecd	point	<pre>vrtu_value_type; vrtu_value_init; vrtu_periodic_value_change</pre>			
SNMP						
VA-UCI-MIB alias ifNumber		erfaces in the u	For the uciIfTable (VA-UCI-MIB) for ciIfTable persistent across reboots and Options uci_alias_ifnumber	8094		
System						
Firmware and configuration rollback	Support automatic rollback of firmware or configuration if router fails to reconnect to Activator after firmware or configuration update using Activation or Active Update. Feature enabled by default.					
TOHDACK	Package	Section	Options	-		
	rollback	core	enabled; timer			
	Support for GW1042 Lite variant with single SIM and no Wifi (machtype: MTATH001)					
GW1042 Lite	(machtype: I	MTATH001)		8117		



Device limiting	Support new			
	Package	Section	Options	7925
(CPX/ORK)	wireless	wifi-iface	maxassoc	

6 Deprecated features

Firmware	Package	Description	Mantis
25.04.35.000	Web/IECD	Removed serial baud rates below 1200 from web UI configuration pages. These values are available via Modbus #1 Serial Speed	8000
25.04.19.000	mobile	Deprecated PPP mode for Quectel and Sierra Wireless modules	7337 7517
		Deprecated Quectel EC20 mobile module support	7337
	strongswan	strongswan.connection.authby deprecated. Now supported by new options localauth; localauth2; remoteauth; remoteauth2	6294
25.02.14.010	WiFi	wireless.wifi-device.type option deprecated	
25.02.14.000	Analogue Relay	Removed analogue relay daemon (ard)	
	dnsmasq	Removed dhcp.dnsmasq.nodaemon	
25.01.40.028	Upnp	Removed miniupnp	
	Wget	Removed wget busybox applet	

7 Known issues

Module	Short Description	Mantis
Event System	Syslog messages only get sent to a single IP address	8046
Firewall	Firewall zone with name longer than 12 characters breaks NAT	7791
GPS	No GPS support for SIMCOM7070	
OSPF	When the remote connection (from a remote OSPF peer) is dropped, OSPF crashes intermittently.	5677
Strongswan	Strongswan memory footprint increases slowly with tunnel restart	5866
Syslog	No web UI support for syslog filter rules	3705
System	Misleading diagnostic message 'failed to killfor device portWAN' generated on network restart or ifup	7817
Web	Web intermittently failing to load when WeConnect is active	7808
	Web UI crashes when option ifname is missing in network configuration	8050
Web/ Administration	Uploading Private Keys to TPM results in web UI error	7874



Web/IPsec	Unable to configure strongswan.connection.disable_mobike,	5437
	strongswan.connection.mobike_send_additional_self Or	
	strongswan.connection.disable_natt via web UI	
Web/Managem ent Users	Unable to configure management users via web UI	5503
Web/Mobile	Missing LTE band selection option when using Hucom/Wetelecom mobile module	8372
Web/Mobile Manager	Error on web UI Mobile Manager when using Hucom/Wetelecom mobile module	8358

8 Problems resolved

Module	Short Description	Mantis
ВСР	Fix BCP crash upon receipt of IPv6 frame	8116
Ethernet	Fix Ethernet ports failing to connect when switching from bridge to port separation on GW6650V series	8305
Event System	Fix syslog message sending to multiple IP address	8046
Firewall	Fix broken protocol values (igp, eigrp, ax.25, etherip, ipcomp, vrrp, 12tp, isi, sctp, fc) used by firewall option proto	7906
	Truncate zone names > 12 chars to avoid breaking firewall	7791
GPS	GPS error messaging improved by using error messages instead of error numbers	6660
GRE	Prevent starting GRE interface if parent interface is missing	8103
HTTP Client	Fix chunk size addition when reporting download status to Activator when using Chunky Downloads that could result in download failure	8023
IECD	Fix parsing of AI scaler when importing data points from CSV file	8199
	Improved data points CSV import feature	8191
IECD/	Fixed issue with sending End of Initialization message in IEC104 slave	8233
IEC104 Slave		
IECD/ IEC61850	Fixed TCP connection drop on IEC104 clock sync processing	8211
IECD/DNP3	Fixed issues in applying scaler to negative MODBUS value for DNP3 to MODBUS protocol conversion	8207
IECD/Modbus	Support Modbus Slave to IEC104 Master command conversion for Set Point Float	8182
IECD/MQTT	Added support for Type ID 20 for IEC101 to MQTT protocol conversion	8135
	Fixed incorrect conversion of IEC101 double points to MQTT	8126
	Fixed issues with converting MQTT to IEC104 Master TypeIDs 9, 13, 48 and 50	8176
L2TP	Fix L2TP initialisation	8035
	Fix privileges which left PPP in a bad state	8071
Mobile	Correctly identify Unitac ML620DE and ML620EU modules in diagnostics. Previously both identified as ML620EU.	8166



	Fix bug introduced in 25.04.26.000 which prevented routers with Quectel modules establishing connection depending on certain operator checks	8247				
	Fix issue with Telit CE910-SL CDMA module not establishing mobile link	8227				
	Fix SIM slot 2 3V/5V issue on Merlin series with Sierra Wireless WP7611 processor					
	Fixes to ensure Unitac modules are initialised correctly	8093				
	Only toggle the RF disable line when module is not present on the USB bus to avoid issues with correct phy detection. This fixes issues with SIM7070E starting on boot.	8114				
	Set minimum firmware software version for Quectel EM060 module to prevent rollback to unsupported firmware	8088				
	Stop flushing conntrack table every time a mobile connection fails to reconnect	8277				
Monitor	Fix Monitor SSH access for SLA uploads	8175				
Multiwan	Fix issue where default gateway is lost on route change	8282				
Network	Fix Ethernet interfaces on Merlin series intermittently failing to restart after a network restart command	8120				
PPP	Allow PPP interface to be up without IP address	8229				
Strongswan	Fix conntrack flushing for strongswan on tunnel change	8249				
Syslog	Fix bad values intermittently generated using firewall recent option	8055				
/RRP	Fix VRRP transition when tracking mobile interface on Merlin series	8020				
Web	Added Security-Policy-Header (CSP) to prevent clickjacking	8087				
	Align reboot loading page with web UI theme	8036				
	Change 'Modem configuration' to 'Mobile Manager Configuration'	7310				
	Ensure lines are visible underneath the login fields	8072				
	Fix formatting error messages in web UI	8255				
	Fix interface colours after firewall zone update	8056				
	Fix pixelated background images	8072				
	Fix web UI crash when option ifname is missing from an interface	8050				
	Remove welcome message from landing page	8072				
	Removed hostname and Westermo logo and link from web UI log in page	8072				
Web/Administ ration	Improvements to reboot scheduling	8125				
Web/Firewall	Add option to Web UI to raise events on zone dropped/rejected traffic. web:	7769				
	cli: firewall.zone.discard_event					
	Ensure firewall zone names are no longer than 12 characters	7791				
Web/GPS	Add option to select mobile device required to use GPS	7943				
	Restore link to google maps	7403				
Web/IECD	Add debug options for IEC61850 to web UI	8215				
	Fixed IECD application restarting correctly when Save & Apply button used and IEC61850 connection is active.	8214				
	used and IEC61850 connection is active.					



Web/ Interfaces	Align up/down indicator centrally				
	Fix unable to select SIM1 or SIM2 from mobile interface SIM configuration option	8007			
	Fix removal of dependent interfaces from configuration	8074			
	Support default route and metric configuration on L2TP interfaces	8073			
Web/Mobile Information	Mobile status information on the web now automatically refreshes every 5 seconds	8272			
Web/PoE Status	Fix 500 error for unknown port power class when port is not physically present	8311			
Web/ Strongswan	Elliptic curve Diffie-Hellman algorithms can now be configured via the web UI when using IKEv2	7730			
WiFi	Default hwmode changed from 802.11g to 802.11ng	3084			
	Fix support for WPA2 with EAP-TLS1.3	8151			



9 Appendix 1: New features history

9.1 Release 25.04.35.000

Event System						
	VA Event System now supports firewall discard event					
Event System	Class	Id	Name	Severity	Event Template	
firewall discard	Firewall	2	DiscardZone	warning	Rule %{p1} triggered: %{p6} from %{p4}:%{p7}(%{p2}) to %{p5}:%{p8}(%{p3}	7769
Firewall						
Firewall discard event forwarding	New option to support raising an event for rejected/dropped traffic in a firewall zone for onward forwarding to an event system target (snmp, syslog, etc) The packet/event rate will be limited to 10/min by default. Use the log limit option to change the default packet rate limit if required.					
Torwaranig	Package		Section	Options	;	
	firewall		zone	discard	_event	
Mobile						
PRI display	Added PRI to mobile stats for Sierra Wireless modules					
SIM7070E diagnostic port	Added su	opor	t for SIMCOM7()70E diagn	nostic port	7979
Monitor inventor	У					
EID Inventory	Support fo	or in	ventory collecti	on of SIM I	EID information	8030
PPP						
	Added support for Bridge Control Protocol for bridging Ethernet packets through a PPP link. Supported for PPP and L2TP protocols.					
BCP support	Package		Section	Options	5	7935
	network		interface	bcp; ma	aclocal	
Scada						
	Added TC	Р ро	rt number to ro	ute config		
Modbus TCP	Package		Section	Options	5	7977
	iecd		port	modbus	s_tcp_server_port	
Optional DNP3	Support o		nal reporting of	DNP3 G40	analog output during	7000
G40 status	Package		Section	Options		7999
	iecd		port	dnp3s_	g40_exclude_intpoll	
SNMP						



EID OID	SIM EID now supported in VA-MODEM-MIB	8029
System		
Unified debug script	Support debug tool which gives a consistent and user-friendly method of enabling debug on various applications. Currently supported for Mobile, IPSec and Multiwan	4677
	cli: debug mobile on	4677
	cli: debug ipsec on	
	cli: debug multiwan on	

9.2 Release 25.04.19.000

Console				
	Support new op	tion for disab	oling the console port	
Console disable	Package	Section	Options	7802
	system	failsafe	console	
Interface				
	Include physica	l ports with e	th-X interfaces in interface status	7900
Interface Status	cli: ifstatus e	eth0 (matches	ce names to show all matches. only eth0) all eth interfaces)	7440
Management Use	ers			
User groups	Support new group configuration which contains a list of <code>allowed_pages</code> . A user can be assigned to multiple groups. This allows a user to be able to visit pages from their own <code>allowed_pages</code> as well as from any assigned groups			7158
	Package	Section	Options	
	management	user	groups	
	_user	group	enabled; allowed_pages	
Mobile				
Airplane mode	Support new option to enter Airplane Mode during the interface back off period			
in backoff	Package	Section	Options	7032
	network	interface	airplane_mode_backoff	
	Support LTE PSM mode for SIMCom7070E mobile module			
LTE power	Package	Section	Options	7841
saving mode	mobile	mobile	sim1_enable_psm; sim2_enable_psm	70.1
	•	•	e processing and support new options for sages are handled	
SMS security	Package	Section	Options	3976
· · · · · · · · · · · · · · · ·	mobile	mobile	sms_read_interval; sms_check_time; sms_past_margin; sms_future_margin	
			Public Pers	



	Support whitel	isting comman	ds allowed to be executable by SMS	-		
SMS whitelisting	Package	Section	Options	6931		
willtelisting	mobile	caller	allowed_commands			
Watchdog timeout behaviour		neout occurs fo	ole action [log reset reboot] to take when or a mobile module. Currently only Section Options main netdev wd action	_ 5719 -		
OpenVPN	mobile		main netdev_wa_detion			
TPM support		-	M. The existing key option should be or the OpenVPN key Options keytype; key ' <tpm-label>'</tpm-label>	7126		
Multiwan			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
Suppress static routes	New option to stransitions to formula Package multiwan		Options suppress_all_routes_on_fail	- 7809 -		
Password Manag	jement					
Multi Factor Authentication	Package dropbear luci system	Section dropbear main pam_auth	Options multi_factor_auth multi_factor_auth type `google'	5339 7152 7154		
Password	Support password lifetime configuration for management users. Does not apply to root password					
lifetime	Package management user	Section user	Options max_passwd_age	7156		
Password	Support config management u	isers password		7194		
regex	Package	Section	Options			
Password reuse	• •		password_regex -use of the last 10 management user root password			
PPP						
Adaptive LCP Echo	interface. This	When enabled LCP echo will only be sent if no traffic is received on the interface. This avoids the situation where PPP is be terminated on a congested PPP link because LCP echos are not received in time Package Section Options				
	network	interface	adaptive_keepalive			
RADIUS						



	Command mass	- £:	ion for NAC Identification with account for	
NAS-Identifier	Support new configuration option for NAS-Identifier with support for %serial and %hostname option values			
option	Package	Section	Options	7347
	system	pam_auth	radius_nasid	
SCEP	3,300	pam_aaa	-ruanus_musiu	
	SCEP now suppo	orts key pair m	anagement in TPM	
TPM support	Package Section Options			
	strongswan	scep_cert	use_tpm; key_label	
SNMP				
Multiwan state OID	Added ifMultiwa	ınState to VA-l	JCI-MIB	6915
Sim detection OID	Added SimIn to	VA-MODEM-M	IB	6915
SSH				
Limit	Support new op (Mantis: 7160)	tion for limiting	g concurrent authenticated user sessions	71.60
concurrent users	Package	Section	Options	7160
users	dropbear	dropbear	MaxConnections	
Strongswan				
IKEv2 Multiple	Support multiple subnets for ikev2			
subnet support	Package	Section	Options	6026
	strongswan	connection	locallanextra; remotelanextra	
T014	Support strongswan keys in TPM. TPM keys are supported via the token secret type. In this case the value of the secret specifies the label of the key to use.			
TPM support	Package	Section	Options	4460
	strongswan	secret	secrettype 'token'; secret ' <tpm-label>'</tpm-label>	
	New option to b	ind an IPSec tu		
	Note: this is only supported for IPv4 ESP tunnel mode.			
VRF support	Package	Section	Options	- 4307
	strongswan	general	vrf	_
	Added support for xauth-eap and eap-radius authentication methods			
XAuth EAP support	Package	Section	Options	
	strongswan	connection	localauth; localauth2; remoteauth; remoteauth2	6294
		radius_serv er	enabled; address; secret; auth_port; acct_port	
System			_	
Busybox	Enable support	for who comma	nd	6788
Change Log	Change log now	records active	e image number and version on reboot	7728



	Support software port mirroring. All ingress and egress traffic on an				
.	interface can be mirrored to an alternate interface				
Port mirroring	Package Section Options	7696			
	network interface mirrorto				
Syslog	New warning message generated to local and remote syslog when any entries stored locally are discarded due to log rotation (Mantis: 7162)	7162			
TPM hashed password	Support new HMAC hashing algorithm for hardware with a TPM. This allows the user to use the HMAC functionality in the TPM as a means of hashing passwords. This is opposed to existing md5 or sha512 hashes and prevents a malicious actor from decrypting as the hashes now require the TPM hardware to be calculated Package Section Options	7155 			
	system system password_hash_algo `hmac'				
VA Events					
	VA Event System now supports ieee8021x event class and events	_			
	Id Name Severity Event Template				
	1 IEEE8021xRestrictingIf notice IEEE8021x restricting on				
	%{p1}				
802.1x events	2 IEEE8021xAllowingAllon notice IEEE8021x allowing all on If $\%\{p1\}$	6528			
	3 IEEE8021xAllowingMAC notice IEEE8021x allowing %{p1} on W{p2}				
	4 IEEE8021xBlockingMAC notice IEEE8021x blocking onIf %{p1} on %{p2}				
Web UI					
	Added new option to disable web UI				
Disable web UI	Package Section Options				
	uhttpd main webui_enabled				
Limit	Support new option for limiting concurrent user sessions				
concurrent	Package Section Options	7161			
users	luci sauth sessionlimit				
LTE band	Show supported LTE bands for enable/disable via Web UI.				
display	web: services->mobile manager->lte				
	Added utility to list and terminate web sessions (Mantis: 7159)				
Session control	<pre>web: system->sessions</pre>	7159			
	cli: sessionctl				
Web UI theme	New restructured web UI with navigation links on left side frame.				
WeConnect					
DCU VPN Concentrator Support	Added support for DCU VPN Concentrator to WeConnect				



9.3 Release 25.03.43.011

No new features

9.4 Release 25.03.43.005

Certificates			
Check both TPM and flash for certificate key	 If the key cannot be found in the location specified in the configuration file, the router will automatically check an alternate location using the following methodology (Mantis: 6820). When configured for PEM key and key cannot be found at the configured location, the router will try to use a TPM key with name corresponding to base file name (/etc/uhttpd.key -> "uhttpd"). When configured for TPM key and key cannot be found in the TPM, the router will try to use file "/etc/<tpm label="">.key"</tpm> 		
Mobile			
FOTA support for Unitac modules	Support FOTA upgrade for Unitac modules		
Neighbour cell information	Added display of neighbouring cell information. Currently only supported on Unitac ML620/660 and Quectel EC200x series cli: vam -n		
Multiwan			
Multiwan upper retry limit for roaming interfaces For 3G roaming connections, and connections with retry_on_senabled, to avoid getting stuck on one SIM, a new multiwan of parameter defines the maximum number of seconds to stay with retry_on_senabled, to avoid getting stuck on one SIM, a new multiwan of parameter defines the maximum number of seconds to stay with retry_on_senabled.			
	Package Section Options multiwan interface retry_connection_max_sec (def:		
	multiwan.interface.ifup_timeout_sec)		
ТРМ			
List TPM keys	Support new diagnostic command to list TPM keys cli: tpm-cli listkeys		

9.5 Release 25.03.43.000

GPS	
GPS MIB support	Added support for VA-GNSS-MIB for retrieval of GPS values
Network	
Dummy interface support	Added support for dummy interfaces. Dummy interfaces are real kernel interfaces (unlike alias interfaces) and support all the configuration options of a static interface. Dummy interfaces are useful in combination with VRFs as they can be isolated from general routing.



Ignore carrier state option	Support new option for static protocol interfaces to ignore carrier state changes. This allows interfaces to stay permanently up even when physic connection is not present (Mantis: 6739)		
	Package	Section	Options
	network	interface	ignore_carrier_state (def: no)
Roaming Manager			
	Added new o	connection retry	options for Roaming Manager feature
Roaming Manager	Package	Section	Options
connection retry options	network	interface	roaming_link_success_time (def: 600 secs); roaming_prefer_best_operator (def: no); roaming_scan_inheritance (def: no)
	multiwan	interface	retry_on_first_fail (def: no)
System			
	Added suppo	ort for time upda	ate via GNSS.
GNSS time synchronisation	Note: Router 6229)	requires GNSS	capabilities and GNSS is enabled (Mantis:
Syncinomsacion	Package	Section	Options
	svstem	timeserver	anss clock source enabled (def: no)

9.6 Release 25.03.03.000

BGP	
BGP MIB support	Added BGP-4-MIB support so BGP information can beretrieved via SNMP (Mantis: 6347)
GPS	
GPS diagnositics	Added new gps diagnositics command
Mobile	
EID retrieval	Support EID retrieval for Quectel, Simcom, Sierra Wireless, Huawei and Telit mobile modules. EID information on the SIMs can be displayed using vam -a command (Mantis: 6236)
FOTA upgrade via CURL	FOTA upgrade can now use CURL to download a firmware image from remote location
FOTA upgrade	Support Quectel FOTA upgrade via locally stored file
SNMP	
LAPB MIB support	Added support for Virtual Access VA-LAPB-STATS-MIB which provides level 2 statistics for the serial interface (Mantis: 4695).
Modem firmware version MIB support	Virtual Access VA-MODEM-MIB modemTable now supports modemFirmwareVersion and modemGsmLtePci (Mantis: 5912)
VA roaming manager MIB support	Added MIB support for VA Roaming Manager (vaRoamingManagerModule) feature to VA-MODEM-MIB (Mantis: 5842)



Monitor			
LTE band and cell diagnostics	Added support for LTE band and cell information in ISAD bins (Mantis 6007)		
VRF support for monitor keepalive	Added support for configuration of VRF domain for Monitor keepalive traps (Mantis: 5983)		
	Package Section Options		
	monitor keepalive vrf		
Multiwan			
Multiwan interface scanning timeout	New multiwan config parameter to extend <code>ifup</code> timeout when a mobile roaming operator scan is active. Used in conjunction with VA Roaming Manager feature, this parameter is added to the normal <code>ifup_timeout_sec</code> used for <code>ifup</code> operations whenever the ifup occurs during a 3G operator background scan, or the ifup itself triggers such a scan, on the modem being used for the current interface.		
	Package Section Options		
	multiwan interface ifup_scanning_timeout_sec (def: 480 secs)		

9.7 Release 25.02.14.033

No new features

9.8 Release 25.02.14.027

Mobile	
EID retrieval	Support EID retrieval for SIMCOM7070E (Mantis: 6236)

9.9 Release 25.02.14.016

No new features

9.10 Release 25.02.14.010

BGP			
BGP MIB eBGP multihop and source peer	specifying s	source addr	nultihop ebgp neighbourhood for the peer and ress for communicating with the peer. Option source ress or UCI interface name (Mantis: 5609)
configuration	Package	Section	Options
support	bgp	peer	ebgp_multihop; source
Peer password	Support for	BGP peer p	password configuration
configuration	Package	Section	Options
	bgp	peer	password



Inbound and outbound route	Support for BGP inbound and outbound route map configuration. Previously it was only possible to specify either inbound or outbound route map.			
map	Package	Section	Options	
	bgp	peer	<pre>inbound_route_map; outbound_route_map</pre>	
Cwatch				
Ping health check	Cwatch now supported re		ing as a monitoring method. Previously only count	
	Package	Section	Options	
	cwatch	watch	<pre>method; icmp_hosts; icmp_attempts; icmp_timeout; icmp_size; icmp_ttl; icmp_reliability</pre>	
Event System				
VRF	Support for routing usin		syslog and email targets to be isolated from general	
	Package	Section	Options	
	va_eventd	target	vrf	
GRE				
		essage and	rt for GRE keepalive tests which sends a single GRE I waits for either reply or timeout. Only relevant for	
	Package	Section	Options	
	multiwan		gre_ka_enabled; gre_ka_timeout_sec	
VRF support for monitor keepalive	Added supp (Mantis: 59		iguration of VRF domain for Monitor keepalive traps	
	Package	Section	n Options	
	monitor	keepali	ive vrf	
Interface				
Interface status logging	interface for determine the setting syst	r defined pe he reliability em.main.auc	cal interface status logging for each configured eriods - day/week/month. Log can then be used to y of an interface over time. Feature is enabled by dit_interface. When enabled, interface up/down pot/interfacelog[*].	
	Log can be displayed via the web UI at status->interface log, or using the command iflog [up down].			
		Section		
	Package	Jection	Options	
	system	main	<pre>audit_interface; audit_interface_log_file; audit_interface_log_size; audit_interface_log_count</pre>	
Routing table display	system Enhanced d	isplay of ro	audit_interface_log_size;	



response time, and other metrics. Package Section Options network interface roaming_enabled; roaming_operator_exclusion roaming_ping_count; roaming_ping_function roaming_ping_interval_ms; roaming_ping_timeout_ms; roaming_ping_timeout_ms; roaming_ping_timeout_ms; roaming_full_scan_timer; roaming_allow_scan_inheritance; roaming_full_scan_window_start; roaming_full_scan_window_end NTP Custom chrony configuration of custom chrony options through web UI system->system->time synchronisation->Custom Chrony configuration options Package Section Options	tion; ;		
network interface roaming_enabled; roaming_operator_exclusion roaming_ordering; roaming_ordering_function roaming_ping_count; roaming_ping_hosts roaming_ping_interval_ms; roaming_ping_timeout_ms; roaming_ping_timeout_ms; roaming_full_scan_timer; roaming_allow_scan_inheritance; roaming_full_scan_window_start; roaming_full_scan_window_end NTP Custom chrony configuration of custom chrony options through web UI system->system->time_synchronisation->Custom_Chrony_configuration options	tion; ;		
Custom chrony Support for configuration of custom chrony options through web UI system->system->time synchronisation->Custom Chrony configuration options			
<pre>configuration</pre>			
· · · · · · · · · · · · · · · · · · ·			
Local clock drift Hidden configuration option system.timeserver.driftfile now defaut factor recording /root/chrony/chrony.drift to record local clock drift factor and redusence synchronisation time on subsequent boots			
Strongswan			
CEP certificate debug level The SCEP client natively supports debug options with 4 levels levels 0,1,2,3 and 4. These can now be configured using new config option debug_level. Set to 0 to disable. (Mantis 5881) Package Section Options			
user option of the certificate. This user gets read access via its group. The owner root, the group is the user. The user is expected to be a member of group. (Mantis: 5908/5913)	Added new config option user, which is the high-level concept of the user of the certificate. This user gets read access via its group. The owner is root, the group is the user. The user is expected to be a member of its		
Package Section Options			
strongswan scep_cert user (def: strongswan) WeConnect			



WeConnect support

WeConnect allows secure remote access to both the network behind the devices and the devices themselves. WeConnect solves the complexity of managing VPNs over the Internet. With WeConnect users can easily and securely connect to any IP-device on the network using their normal PC, smartphone or tablet.

Contact your local Westermo reseller or visit weconnect.westermo.com for further information.

Package	Section	Options
weconnect	weconnect	<pre>weaddress; weint_name; confver; wetoken; weotp; rip_int</pre>

9.11 Release 25.01.40.028

Ethernet			
Software watchdog			og script to check switch MIB counters and reset if W1042 hardware.
Mobile			
Mobile backoff configuration	mobile inter	rfaces. This ore backoff	configuration of backoff and reconnection timers on allows for configuration for the number of ifup and the amount of time to wait before connection retry timer can be configured to incrementally
	Package	Section	Options
	network	interface	failures_to_backoff; backoffminutes
Mobile custom initialisation string	at mobile st independer • The	tartup and some some some tand some some some some some some some some	_
	• The	response t	o wait for
	• The	timeout to	wait for the response
	Package	Section	Options
	mobile	main	sim1_custom_pre_init_at_string; sim2_custom_pre_init_at_string; sim1_custom_pre_init_at_string_timeout; sim2_custom_pre_init_at_string; sim1_custom_post_init_at_string; sim2_custom_post_init_at_string; sim1_custom_post_init_at_string_timeout; sim2_custom_post_init_at_string_timeout
Reset LOCI file	New option	sim[1 2]_1	pci_file_reset_enabled when enabled will lead to a
content on SIM on startup	fresh opera	tor search a	at radio module startup instead of the module trying t used network again
	Package	Section	Options
	mobile	main	sim1_loci_file_reset_enabled; sim2_loci_file_reset_enabled



Roaming templates multiwan group	•	for configurati		multiwan exclusive group. Previously this
	Package	Section		Options
	mobile	roaming_tem	plate	multiwan_exclusive_group
SNMP				
CDMA 450 MIB support	Added CDM Code	A 450 MIB sup	port to	vaModem.mib for EC/IO, DRC and PN-
	MIB	De	scripti	on
	vaModem.	29 EC	/IO	
	vaModem.	30 DF	RC .	
	vaModem.	31 PN	-Code	
LTE band MIB	Added LTE	oand to vaMode	m.mib	
support	MIB	De	scripti	on
	vaModem.		E band	
Strongswan				
Interoperability improvements	New options added to strongswan configuration for better interoperability with 3rd party vendor peers.			
	Package	Section	Opti	ons
	strongswa	n connection		ble_mobike; ike_send_additional_self;
SCEP CA fingerprint validation		ainst the finge		which specifies a fingerprint that can be (MD5 or SHA1) of a CA certificate during
	Package	Section	C	Options
	strongswa	n scep_cert	f	ingerprint
System				
Password hash	Support for algorithm.	configurable p	asswo	rd hashing algorithm using SHA-512
		-		d hash then firmware cannot be rolled back rt SHA-512 ie prior to this release.
	Package	Section O	ptions	
	system	main pa	asswd_	_hash_algo
Reset	_	_	_	on files are now deleted when router is reset button press

Note: New features prior to CPX-25.01.43.028 have been archived



10 Appendix 2: Problems resolved history

10.1 Release 25.04.35.000

Module	Short Description	Mantis
Data Usage	Fix data usage bringing down interface when monthly usage limit reached	7759
Event System	Fix missing interface names in VA event messages generated by the firewall using the recent option.	8037
GPS	Fix gpspeek location information	7980
HTTP Client	Fix chunk size addition when reporting download status to Activator when using Chunky Downloads that could result in download failure	8023
L2TP	Fix L2TP initialisation	8035
Mobile	Disable va-mobile and execute AT+CFUN=0 before powering down SIMCOM7070 modem to avoid module not reinitialising on USB bus	7996
	Ensures signal strength and registration status information is refreshed as part of the check whether or not the radio module is registered with a PLMN and the signal strength is sufficient. Fixes connectivity issue when last reported signal strength was -113dBm or less.	7919
	Fix incorrect detection of registration status while in GPRS mode	7945
	Power cycle the SIMCOM7070E modem if it starts in EDL mode	8014
	Reset SIMCOM module authentication details to avoid using stored credentials when username/password not explicitly set in configuration	8013
Network	Fix link loss when changing from bridge to single port	7937
PPP	Fix option record support	8022
Roaming Manager	Ignore test operators in roaming scan	8001
Scada/ IEC61850	Fix description in the IEC61850 Slave side data point for DO field	8019
Scada/ Modbus	Fix DNP3S to Modbus conversion issues for select operate	7999
	Fixed bug in converting MODBUS HR register reads to DNP3S points (G30 and G40) mapped to same HR index	7999
System	Fix memory crash on GW1150 series under heavy load	4681
	Re-enable nano support	7998
	Suppress UCI error on version -a command if mobile module is not initialised	7984
Web/ Interface	Fix network interface colours to reflect up/down status	6536
	Update interface pages to show firewall zones as colours	7988
Web/Real Time Graph	Only show UCI network interfaces on the Realtime Traffic screen	7946



10.2 Release 25.04.19.000

Module	Short Description	Mantis
802.1x	Fix 802.1x authentication	4290
		7464
	Fix 802.1x restart after ifup or cable unplug/plug	7530
Activator	Fix issue with multiple downloads from different services (active update, inventory, audit) running simultaneously	6321
Cwatch	Change Cwatch 'Interface does exist' message to NOTICE severity	7078
DHCP	Fix corrupted IA address when sending OPTION_IA_N	7424
Ethernet	Fix Ethernet ports intermittently reflecting incorrect state when bridging	7795
Event System	Correctly handle double quotes in event target cmd_template value	5736
	Fix $\mathtt{va_event}$ syslog messages showing with no space between date and serial number	7513
Firewall	Support vrrp as valid protocol option	7906
GRE	Validate configured keys are unique	6769
HTTP Client	Include all CPUs in interrupt count value in hdl request field ${\tt irq_cnt}$	6228
Mobile	Added error messages for failed connection attempts for Quectel modules in Ethernet mode	7899
	Allow backslash '\' in username and password	7360
	Custom interface DNS now supported by Unitac modules	7192
	Ensure PDP context is deactivated before attempting to establish connection to avoid issue with connection attempt	7168
	Fix band selection for SIMCom7070E module	7833
	Fix EID detection when APDU contains the tag and length	7522
	Fix operator scan	7693
	Fix Quectel registration status poller	7484
	Fix Unitac module FOTA upgrade on GW6650V and Merlin4700	7761
	Fix va_mobile failing to start if LTE band list is empty	7495
	Fixed network status constantly changing textual description (LTE/LTE-M) for used radio technology	7340
	Fixes to ensure the manual network operator selection is executed in the right order	7797
	Improve behaviour on network down for QMI connections to ensure reconnection after network outage	6325
	Improve the handling of +CREG responses so that it also handles CREG mode 2	7880
	LTE band locking configuration option <code>simX_lte_bands</code> now supports space separated bands	
	Log a warning that GNSS is not supported for SIMCom7070E mobile module	7822
	sendsms command now handles '+' at the beginning of international numbers	
	Unitac modules now use wwan0 interface rather than eth0	6899



Multiwan	Produce warning for interfaces that do not exist	7857
Network	Add interface name and state for aliases to network_status	6716
	Fix dependant interfaces starting correctly on a network restart	7598
	<pre>ifup/ifdown now correctly validate the UCI interface name before execution</pre>	6276
	Remove the minimum IPv6 fragment size check	7320
		7324
		7325
		7326
OpenVPN	Allow tun or tap setting to create interfaces correctly.	7114
	Don't create new linux and uci interface on openvpn restart	7735
	OpenVPN interfaces are no longer deleted on ifdown/network restart event	7871
PPPoE	Fix PPPoE interface on an Ethernet port not automatically starting on boot	7924
	When PPPoE link is on a VLAN, it is no longer necessary to configure a dummy UCI interface for the underlying device in order for the VLAN to be created	7924
SCEP	Fix certificate expiration date calculation	7572
	SCEP ATQ time now synchronised with NTP	7083
SNMP	Fix UCI MIB ifName truncation	6981
	SNMP engineID now has fixed value that persists through reboot	7355
		7358
Strongswan	General improvements to memory usage	
Syslog	Fix syslog to use local time instead of UTC	7240
System	Adds the ability to define a COMMENT environment variable when invoking any process for display by $\mathtt{ps}\xspace$ command	7020
	Fix minimum machtype firmware version checking	7717
		7722
		7714
	Fix misleading `cannot find device' messages on network restart or <code>ifup</code>	7798
	Panic log now contains timestamp on crash events	5608
	Replace invalid spaces in hostnames with '-' at run time	7829
TACACS	Fix IPv6 support	6620
TPM	Fix error message when ${\tt tpm-cli\ flush}$ command is executed twice in a row	6010
VA Event	Fix buffer overflow crash and add new internal warning event upon	7176
System	event buffer overflow	7163
VRRP	Allow multiple groups in vrrp status command	7246
Web	ADSL configuration options no longer displayed when not supported on the hardware	6919
	Fix issue socket closing before HTTP data is complete which can result in UI not displaying correctly	6738 7752
	Fix reboot via web UI	7574
	Prevent capitalisation of configuration section names	7856



Web/ Interfaces	Ensure interface names are not automatically capitalized on the web UI	7678
	Remove PPTP protocol from available interface protocols	7354
Web/ Multiwan	Support multiwan.interface.state_transition_hook configuration via the web UI $$	5433
Web/ OpenVPN	Implement dependency between local and nobind option to avoid OpenVPN failing to start when both enabled in config	6819
Web/ WeConnect	Added support for DCU VPN Concentrator configuration options	
Web/802.1x	802.1x web UI enhancements; add file upload for certs and keys; Only display bridge interfaces as available 802.1x supplicant interfaces	6528
Web/Dynamic DNS	Restart DDNS when settings are changed from web UI	6491
Web/Firewall	Fix add and edit of firewall zones and rules via web UI	7573
	Support firewall rule chain option	6898
	web: security->firewall->traffic rules	
	cli: firewall.rule.chain	
Web/ Interfaces	Allow configuration of an MTU higher than 1500 bytes	7534
Web/Mobile	Added display of LTE bands supported by SIMCom7070E	7565
	Fix va_mobile restart on save & apply via web UI	7494
	Simplify mobile configuration using tabs via web UI	7707
Web/Mobile	Show supported LTE bands for enable/disable via Web.	
Manager	web: services->mobile manager->lte	
Web/Realtime	Fix display of Realtime Graphs for mobile interfaces	7029
Graphs	web: status->Realtime Graphs	
Web/Status	Only show hardware capable features	6966
·	Only show multiwan status when enabled	6966
Web/System	Fix duplicate firewall package in configuration export	6904
	Support missing configuration options for SSH connection identity, verbose and VRF via web UI	6703
	web: security->ssh->Identity	
	cli: dropbear.dropbear.Identity	
	web: security->ssh->Verbose	
	cli: dropbear.dropbear.verbose	
	web: security->ssh->VRF	
	cli: dropbear.dropbear.VRF	=
WeConnect	Add missing ripd and openuph packages during provisioning	7687 7688
	Fix auto generated RIP configuration to ensure WeConnect correctly	7427
	connects in a Ethernet bridge scenario and also reestablishes on	7539
	disconnect.	7591
	Fix duplicate interface creation on connect	7547
	Fix support for WeConnect	6793
		7218



	HTTPS support for DCU VPN Concentrator auto enrolment	6961
	Network status diagnostics now correctly show WeConnect interface IP address	7682
WiFi	Use serial number as base for WiFi interfaces	6256

10.3 Release 25.03.43.011

Module	Short Description	Mantis
Certificates	Improve error reporting for common issues with HTTPS certificates	6987
Mobile	Added a module reboot after executing a factory reset of the Unitac module	
	Added an extra delay before issuing the AT command to switch the Unitac modules into ECM mode.	
	Ensure Unitac module comes back in ECM/VLAN mode after factory reset	
	Record Unitac AUX antenna values regardless of MIMO state	
	Use Unitac-specific AT commands AT!UBAND, AT!UTEMP and AT!UREBOOT instead of GCT commands	
TPM	Don't allow loading a new key if a key with the same label is already present	
Web/Event System	Support configuration of Event System Digital Input change event input number and value via web UI	6839
	web: services->va event system->event filters->Input Number	
	<pre>cli: va_eventd.forwarding.input_number</pre>	
	web: services->va event system->event filters->Input Value	
	cli: va_eventd.forwarding.value	
Web/OSPF	Support configuration of OSPF VRF via web UI	6964
	web: network->ospf->global settings->VRF	
	cli: ospfd.routing.vrf	
Web/Realtim	Fix web UI real time graphs for QMI mobile connections	7029
e Graphs	web: status->Realtime Graphs	

10.4 Release 25.03.43.005

Module	Short Description	Mantis
Activator	Set model URL parameter to uimodel rather than machtype in updates to Activator	6761
CLI	Improve error message for uci show xy when xy does not exist	
Ethernet	Add arp-scan utility to DRS, ORK and SXL families for consistency with EDG family	5829
	cli: arp-scan -l	
Firewall	Fix variable name clash in zone option presence test causing occasional restart issue	
	Simplify firewall forwarding within a bridge by avoiding calls to iptables	



Firmware	Prevent downgrade of router firmware to a version that is incompatible with the on board Sierra Wireless module	6878
Mobile	Add ${\tt dmcli}$ tool for use diagnosing Unitac module problems on GW1042 models	6906
	Ensure ARP is not turned off for the Unitac Ethernet interface causes problems with the firmware upgrade tool.	
	Ensure NOARP flag is set on mobile Ethernet devices to avoid the ARP table from filling up with entries from the mobile connection	6676
	Ensure the SMS format is set correctly and interfaces restarted after Verizon provisioning.	
	Fix handling of 5G status when operating in an 5G SA network	
	Fix to ensure the Verizon attach APN is set correctly	
	Only restart interfaces when Network Initialisition was indicated in OMADM	
	Switch to AT!GSTATUS to retrieve signal information for Unitac modules	
OpenVPN	Fix privileges in OpenVPN to allow automatic restarts and fix open SSL errors in WeConnect	6793
SNMP	Correct vaUciMib implementation so that it matches the previous implementation	6903
SNMP/GPS	Fix GPS heading in MIB from degrees to micro degrees	6901
System	Fix issues when config files have execute permissions set and configuration audit is enabled	
VLAN	Fix VLAN bridging on Merlin and GW6650V models	6768 6844
Web	Fix error message typo when SSL subsystem fails to initialise	
	Print openSSL errors when init, cert load or key load fail	
Web/ Interfaces	Avoid restarting all interfaces when adding new interface via web UI	6922 6923
Web/Cwatch	Fix display of bridge interface on Cwatch interface list	6824
Web/System	Restore javascript validation preventing underscores in system hostname	4555

10.5 Release 25.03.43.000

Module	Short Description	Mantis
Activator	Fix Activator active update command returning incorrectly parsed IPv6 addresses	4727
BGP	Fix local VRF IP subnet not being advertised over WAN VRF using a BGP instance in the same VRF $$	6799
CWATCH	Cwatch now ignores non-existing UCI network interfaces	6644
Cwatch	Fix cwatch using cached interface values rather than current values which caused cwatch to intermittently miss state changes	6784
Ethernet	Fix Ethernet switch health check on GW1042 when a configured VPN policy matches health check	5758
Failsafe	Failsafe mode now uses SSH instead of telnet access	6663



Firewall	Insert the MARK configuration rule before the $\mathtt{redirect}$ rules in the firewall table	5405
LED	Fix Ethernet port A green LED not illuminating on GW1042 series	4511
Mobile	Add MTU detection for Unitac modules	
	Ensure MTU does not exceed 1500 bytes on QMI links	6567
	Ensure Quectel EC25/EG25 modules use GSM format for SMS messages	
	Fix crash when switch_sim command is executed with no value	
	Fix interface name and type for Unitac modules on Merlin series	
	Fix missing LTE band information on older Unitac firmware	6630
	Fix signal strength detection on older Unitac modules	6805
	Prevent crash when handling SIMs with invalid ICCID	6635
	Prevent crash when no SIM slot specified for SIM switch command	
	Rename 'phone number' to 'MSISDN' in mobile stats	
	va-mobile no longer automatically changes GNSS configuration as this is now done in manufacturing	6659
Monitor	Fix Monitor Keepalive configuration changes taking effect immediately when changed from web UI or Activator	6650
NTP	Improvements to chrony operation for interface state changes	6631
РР	Fix connection issue when two ppp links have similar UCI name	6654
Roaming Manager	Retry existing connection after routine disconnect when using Roaming Manager feature	
SNMP	Fix mibwalk error on .1.3.6.1.4.1.2078.3.1.2.4.2 when walking VA-MODEM-MIB::roamingOp* series of values	6618
	Fix SNMP configuration using TCP protocol	5930
SSH	Fix SSH login via private and public key.	6425
ΓACACS	Fix ipv6 address support	6620
/RF	Fix DNAT behaviour for alias interface within VRF	6705
Web	Fix slow web SSL access when using keys from TPM	6734
	Sort web UI drop down headings	5909
Web/ IPsec	Fix error on saving of configuration general section	6281
Web/ Multiwan	Allow multiwan configuration via web UI when no multiwan config options exist in configuration file	
Web/ Network	Show colour codes for interface status in network overview	6536
Web/ OpenVPN	Automatically add and remove OpenVPN network interfaces	6296
Web/BGP	Fix BGP network option for IP address/subnet input rather than interface name	6619
	web: network->bgp->global settings->Network	
Web/Firewall	Fix summary page showing rules with option enabled '1' in configuration file as disabled	6765
Web/HTTP Client	Support configuration of Http Client certificate key format web: services->http client->advanced->Certificate Key Format cli: httpclient->httpclient->KeyFormat	5792



Web/HTTP Server	Support configuration certificate keys in TPM web: services->http server->Certificate Key Format cli: uhttpd.uhttpd.keytype [PEM TPM]	6756
Web/IPsec	Web UI IPSEC configuration improvements	6281
Web/Mobile	Correct display of mobile interface type on web UI interface overview page	6787
Web/Status	Add download button for kernel and system log web: status->System Log web: status->Kernel Log	6794
Web/System	Fix firmware flashing error mesage	6286
Web/VRRP	Add support for configuration of VRRP Group Multicast Source IP web: network->vrrp->vrrp group configuration-> Multicast Source IP cli: vrrp.vrrp_group.mcast_src_ip	4057
Web/WiFi	Removed 40 MHZ channel option from web UI for GW1042 series	6706

10.6 Release 25.03.03.000

Module	Short Description	Mantis
CWATCH	Ensure cwatch can handle comma separated ping destinations	
Ethernet	Ensure Ethernet ports aren't bridged during startup on GW1042 to avoid leaking traffic between LAN segments during reboot	5906
	Ensure that bridge interface in GW1042 uses MAC of first Ethernet interface	2664
	${\tt ifup}$ now preserves VLAN interfaces when configuration has non VLAN and multiple VLANs attached to the same Ethernet interface	6247
	Increase frame size limit to accommodate large VLAN packets	6307
Event System	Fix boot success event	5927
GRE	Fix GRE keepalives	6554
Mobile	Add data-only configuration for Quectel EP06 module	
	Add display of additional Unitac signal values to \mathtt{vam} command and web UI	
	Add switch to add switch to data-centric mode for Quectel EC25 and SIMCOM modules	
	Added 5G network registration status	
	Added PCI display for Unitac modules	6251
	Disable the APNs when connection is terminated for Unitac modules	6484
	Ensure that Verizon APN is correct for default/initial bearer	6154
	Enter airplane mode before attempting to change the default LTE bearer to avoid issues with SIM failover	5991
	fix chat command failing if previous chat aborted	6210
	Fix crash when LTE band retrieval for SIMCOM fails	
	Fix ESN display where leading zero's were being omitted	6345
	Fix for SMS received by Quectel EG25G via IMS in Verizon network	6594



	Fix incorrect reporting of RSSI when using Unitac mobile module	6437
	Fix multiwan to run with default group when no group name specified	
	Fix to prevent the modification of the Verizon attach bearer	6043
	Fix va_roaming ignoring Stat=0 operators in roaming scan	6184
	Ignore network provided DNS addresses if option DNS configured	6372
	Improvements to operator scan:	
	 Now commence an operator scan as follows; AT+COPS=2 (detach from network); AT+COPS=0;+COPS=? (reattach and commence scan, all in one operation) 	
	 AT+COPS=? timeout increased to 190 seconds 	
	 automatically retry a failed AT+COPS=? command if it fails within 15 seconds 	
	vam roaming now includes scan duration in seconds	
	Incorrect SINR reported for Quectel modules	5951
	Mobile connection no longer dropped when 2 nd antenna is docinnected when using Unitac modules	6446
	Prevent +CGEV: NW DETACH trigger warnings in the logs	6616
	Re-connect to network automatically if AT+CGATT=1 fails	
	Support new option to enable MIMO on Unitac modules (disabled by default).	6499
	<pre>web: services->mobile manager->advanced->Enable MIMO for Unitac radio Modules</pre>	
	cli: mobile.mobile.unitac_mimo_enabled	
	VA Mobile roaming diagnostic now shows roaming info for all modems by default	
	cli: vam roaming	
Network	Ensure $ifdown$ kills all $ifup$ processes on the same interface and not just the child processes	
	Fix dependent interface behaviour when parent WAN interface is using QMI mobile interface	6493
	Fix repeated ifup race condition on bridged interfaces	6265
QoS	Fix QoS initialisation	6560
Routing	Enable FRR vty_enabled option in user interface	6613
SCEP	Added certificate expiry check during re-renrollment	6235
	Change new cert and key permissions when they are installed at the end of the SCEP process. Also adjust the CRLs directory to allow strongswan write access for runtime CRL downloads.	5908
	Fix intermittent issue where only one SCEP request was sent when multiple SCEP clients were configured	6523
	Fix loading of SCEP CA certificate	6525
	Strongswan is now restarted after SCEP renewal to ensure the peer correctly deletes the existing IKE_SA	6190
SNMP	Fix creation of SNMPv3 traps	5943
	Fix failing snmpwalk on vaModem MIB when no roaming info available	5922



Strongswan	Allow IPSec tunnels to start when CA certificate download fails and blocking is disabled in <pre>scep_cert</pre> config	6324
	Do not split long PSK into separate lines which would cause PSK to be read incorrectly and Phase1 failure	6537
	Remove FlexVPN GRE IP addresses on tunnel termination	5924
	Fix IKE SA delete being sent with correct message id to ensure IPSec peer does not discard	6246
Syslog	Fix multiwan errors in log when multiwan not configured	6489
System	Changed password hash algorithm option value to a ListValue cli: list system.main.passwrd_hash_algo	5001
	Fix auditing of DMVPN configuration using option audit_cfg	
	Prevent download of incorrect firmware family	
TACACS	Fix tab correction for TACACs+ user login via SSH	6527
TPM	Fix RSA key loading on big endian platforms	
	Improve support for TPM access from multiple processes to avoid TPM being locked by another process	6483
User Limits	Fix Procrustes user limit events	6538
Web	Fix web UI intermittently advising router is running in factconf when in config1	6547
	Improvements to web UI performance and load times	6178
Web/ Interface	Added mtu configuration opton for PPPoEoA and PPPoA ADSL interfaces	5702
	Fix default gateway handling for DHCP protocol	6601
Web/ OpenVPN	Do not add $key_direction$ option when set to its default value (bidirectional) when OpenVPN configured via web UI	6063
Web/BGP	Fix BGP network option for IP address/subnet input rather than interface name	6619
	web: network->bgp->global settings->Network	
Web/Mobile	Prevent option $ifname$ configuration being added to mobile interfaces when configured via web UI	6501
Web/SNMP	Improvements to web UI SNMP configuration	
Web/VA Event	Add length check in web UI for <code>snmp_auth_pass</code> and <code>snmp_priv_pass</code>	
Web/WiFi	Add WPA Enterprise configuration to web	5963
WiFi	Fix ifup transmission issue when WiFi is bridged with an Ethernet interface	6514

10.7 Release 25.02.14.033

Module	Short Description	Mantis
Download	Fix interrupted download when va_vars incorrectly states image not found. Download now correctly continues rather than starting again.	6354
Mobile	Fix duplicated ICCID when using WP76xx-AU module on Merlin4600 series.	6352



	Fix SIM7070E with B10 firmware intermittently not being detected on boot.	6396
	Fix Unitac module detection (broken in release 25.02.14.030)	6387
TACACS	Fix TACACS behaviour when router is configured to only authorise authentication for SSH access (or other configured PAM services). Previously all authentication requests were sent to TACACS server instead of SSH only.	6050
TPM	Fix HTTPS incoming connection activation with key stored in TPM on Merlin4600 series.	6367
	Flush transient objects from TPM RAM upon session open on Merlin4600 series.	

10.8 Release 25.02.14.027

Module	Short Description	Mantis
Download	Fix size calculation when image download exceeds 10M	6033
	Increase time limit for image download to 5 hours (previously 2 hours)	6266
HTTP Client	Set download minimum rate limit to 1kBps	6266
PPPoE	<pre>ifup <ifname> now correctly re-establishes when <ifname> is a PPPoE</ifname></ifname></pre>	6241
	link and is already up	
Serial	Fix serial LED settings when option serialPortName is configured on GW2124P series	6219
WiFi	Fix intermittent incorrect WiFi interface name generated by ifup command on WiFi interfaces	6253

10.9 Release 25.02.14.016

Module	Short Description	Mantis
GPIO	Merlin4600 series digital input values changed to match GW2020 series for SCADA operation compatibility 0 = input not detected/open/low 1 = input detected/closed/high	
RTUD	RTUD auto generate config option now defaults to off in both web UI and router	6075
	web: scada->rtud->main settings->Auto generate configuration	
	<pre>cli: rtud.rtud.point_auto_config_on</pre>	
	Fix defaults for RTUD so web UI no longer shows errors when saving	6075

10.10 Release 25.02.14.010

Module	Short Description	Mantis
Activator	Added RADIUS support to active updates	3514
	<pre>Information sent to Activator via httpclient now includes all previous values: imei, sim1_iccid, sim2_iccid, hw_rev, sim1_imsi and sim2_imsi</pre>	



Dropbear Remove stale sshd service files causing issues with telnet access 5533	Busybox	Truncated ping responses now no longer discarded but noted in the ping response message	5658
Ethernet Binhancements to GW1042 Ethernet health check to avoid configuration blocking health check pings. Now allow ping broadcasts through based even if default output set to drop in firewall and dynamically add strongswan bypass policy rule Fix default MAC address for Merlin4600 Ethernet ports Fix LED port D behaviour on GW3300D Restored missing arp-scan functionality on GW6600V cli: arp-scan (ip]-1) Event Connection tester type link now correctly checking link state Fix connection tester type link now correctly checking link state Fix connection tester system->connection tester->Fing Source cii; va_eventd_conn_tester.ping_source Fix connection tester when using UCI interface name for ping source Fix connection tester when using UCI interface name for ping source Fix to ensure failed SNMP traps are retried on delivery failure. Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfacea->L2TP->advanced settings->TX Speed cli: network-interfacea->L2Tp->bps_tx web: network-interfacea->L2Tp->bps_tx xe: network-vinterfacea->L2Tp->bps_tx Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix Pronnectivity when using Huawei 709 with firmware 1.652.65.00.00	DHCP	Improved reporting when external DHCP server detected	5520
blocking health check pings. Now allow ping broadcasts through base0 even if default output set to drop in firewall and dynamically add strongswan bypass policy rule Fix default MAC address for Merlin4600 Ethernet ports Fix LED port D behaviour on GW3300D Restored missing arp-scan functionality on GW6600V cli: arp-scan (ip -1) Event Connection tester type link now correctly checking link state 5535 Fix connection tester failing when ping source is specified web: aervicea-vaw event ayatem->connection teater->Ping Source eil: va_eventd.conn_tester.ping_source Fix connection tester when using UCI interface name for ping source fix crash when invalid options are specified in config Fix intermittent delay in sending syslog events Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed oli: network.interfaces->L2TP->advanced settings->TX Speed oli: network-interfaces->L2TP->advanced settings->TX Speed cli: network-interfaces->L2TP->badvanced settings->TX Speed oli: network-interfaces->L2TP->badvanced settings->TX Speed oli: network-interfaces->L2TP->badvanced settings->TX Speed cli: network-interfaces->L2TP->badvanced settings->TX Speed oli: network-interfaces->L2TP->badvanced settings->TX Speed oli: network-sinterfaces->L2TP->badvanced settings->TX Speed oli: network-sinterfaces->L2T	Dropbear	Remove stale sshd service files causing issues with telnet access	5533
Fix LED port D behaviour on GW3300D Restored missing arp-scan functionality on GW6600V cil: arp-scan (ip - I) Event Connection tester type link now correctly checking link state Fix connection tester failing when ping source is specified web: services->va event system->connection tester->Ping Source cil: va_eventd.conn_tester.ping_source Fix connection tester when using UCI interface name for ping source Fix crash when invalid options are specified in config 1977 Fix intermittent delay in sending syslog events Fix to ensure failed SMMP traps are retried on delivery failure. Fixes for crash caused by recursion 4734 GRE Integrate keepalive responder to gre interfacesovery GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cil: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cil: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cil: network.interface.l2tp_bps_tx Meb network->interface.l2tp_bps_tx Meb network->interface.l2tp_bps_tx Me	Ethernet	blocking health check pings. Now allow ping broadcasts through base0 even if default output set to drop in firewall and dynamically add	5758
Restored missing arp-scan functionality on GW6600V cli: arp-scan (ip - i) Event System Connection tester type link now correctly checking link state Fix connection tester failing when ping source is specified web: services->va event system->connection tester->Ping Source cli: va_eventd.conn_tester.ping_source Fix connection tester when using UCI interface name for ping source Fix crash when invalid options are specified in config Fix intermittent delay in sending syslog events Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.12tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.12tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.12tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.12tp_bps_tx web: network-oneme in XL2TPD package Fix GW1400 series memory corruption Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00		Fix default MAC address for Merlin4600 Ethernet ports	5740
Cli: arp-scan (ipi- I) Event System Connection tester type link now correctly checking link state Fix connection tester failing when ping source is specified web: services->va event system->connection tester->Ping Source cli: va_eventd.conn_tester.ping_source Fix connection tester when using UCI interface name for ping source Fix crash when invalid options are specified in config Fix intermittent delay in sending syslog events Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network-interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network-orane in XL2TPD package Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00		Fix LED port D behaviour on GW3300D	5869
Fix connection tester type link now correctly checking link state Fix connection tester failing when ping source is specified web: services->va event system->connection tester->Ping Source cit: va_eventd.conn_tester.ping_source Fix connection tester when using UCI interface name for ping source Fix crash when invalid options are specified in config Fix intermittent delay in sending syslog events Fixes for crash caused by recursion GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network-interfaces->L2TP->advanced settings->TX Speed cit: network.interfaces->L2TP->advanced settings->TX Speed cit: network-interfaces->L2TP->advanced sett		Restored missing arp-scan functionality on GW6600V	5829
Fix connection tester failing when ping source is specified web: services->va event system->connection tester->Fing Source cli: va_eventd.conn_tester.ping_source Fix connection tester when using UCI interface name for ping source Fix crash when invalid options are specified in config Fix intermittent delay in sending syslog events Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->badvanced settings->RX Speed cli: network.interface.l2tp_bps_rx L2TP Fix vendor name in XL2TPD package Memory Fix GW1400 series memory corruption Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00		cli: arp-scan (ip - I)	
web: services->va event system->connection tester->Ping Source cli: va_eventd.conn_tester.ping_source Fix connection tester when using UCI interface name for ping source Fix crash when invalid options are specified in config 1977 Fix intermittent delay in sending syslog events 4902 Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_rx H2TP Fix vendor name in XL2TPD package Memory Fix GW1400 series memory corruption Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00		Connection tester type link now correctly checking link state	5535
Fix connection tester when using UCI interface name for ping source Fix crash when invalid options are specified in config 1977 Fix intermittent delay in sending syslog events 4902 Fix to ensure failed SNMP traps are retried on delivery failure. 5527 Fixes for crash caused by recursion 4734		Fix connection tester failing when ping source is specified	5526
Fix connection tester when using UCI interface name for ping source Fix crash when invalid options are specified in config Fix intermittent delay in sending syslog events Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.l2tp_bps_rx L2TP Fix vendor name in XL2TPD package 5771 Memory Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00			
Fix crash when invalid options are specified in config Fix intermittent delay in sending syslog events Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion 4734 GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.l2tp_bps_rx L2TP Fix vendor name in XL2TPD package 5771 Memory Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00		cli: va_eventd.conn_tester.ping_source	
Fix intermittent delay in sending syslog events Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion 4734 GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.12tp_bps_tx web: network->interfaces.12tp_bps_tx web: network->interfaces.12tp_bps_rx L2TP Fix vendor name in XL2TPD package 5771 Memory Fix GW1400 series memory corruption Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00		Fix connection tester when using UCI interface name for ping source	5828
Fix to ensure failed SNMP traps are retried on delivery failure. Fixes for crash caused by recursion Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.l2tp_bps_rx L2TP Fix vendor name in XL2TPD package Fix GW1400 series memory corruption Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix Crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00		Fix crash when invalid options are specified in config	1977
Fixes for crash caused by recursion GRE Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.l2tp_bps_rx L2TP Fix vendor name in XL2TPD package Fix GW1400 series memory corruption Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 1.652.65.00.00		Fix intermittent delay in sending syslog events	4902
Integrate keepalive responder to gre interfacesso every GRE interface will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.l2tp_bps_rx L2TP Fix vendor name in XL2TPD package Fix GW1400 series memory corruption Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 1.652.65.00.00		Fix to ensure failed SNMP traps are retried on delivery failure.	5527
will automatically start keepalive responder and reply to all GRE keepalive messages L2TP Add new debug options for L2TP speed web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.l2tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.l2tp_bps_rx L2TP Fix vendor name in XL2TPD package 5771 Memory Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00		Fixes for crash caused by recursion	4734
web: network->interfaces->L2TP->advanced settings->TX Speed cli: network.interface.12tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interfaces->L2TP->advanced settings->RX Speed cli: network.interfaces.12tp_bps_rx L2TP Fix vendor name in XL2TPD package 5771 Memory Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00	GRE	will automatically start keepalive responder and reply to all GRE	5249
cli: network.interface.12tp_bps_tx web: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.l2tp_bps_rx L2TP Fix vendor name in XL2TPD package 5771 Memory Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00	L2TP	Add new debug options for L2TP speed	5769
cli: network->interfaces->L2TP->advanced settings->RX Speed cli: network.interface.l2tp_bps_rx L2TP Fix vendor name in XL2TPD package 5771 Memory Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00		web: network->interfaces->L2TP->advanced settings->TX Speed	5770
cli: network.interface.l2tp_bps_rx E2TP Fix vendor name in XL2TPD package 5771 Memory Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00			
Memory Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00			
Memory Fix GW1400 series memory corruption 5620 Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00			
Mobile Add LTE band information to /var/state/mobile when using Huawei ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00			
ME909U module (firmware > 12.63x.x) Added Operator Code (5-digit MCC/MNC) and Cell ID to vam -a command Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00		·	
Ensure HDR credentials are always provided when needed for CDMA connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00	Mobile	ME909U module (firmware > 12.63x.x)	3278
connections. Fixes situations where this information could be lost by module or config transferred to another router. Ensure LTE band lock stays enabled on Hucom modules 5447 Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00			
Fix crash when LTE band retrieval for SIMCom fails Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00		connections. Fixes situations where this information could be lost by	5735
Fix ICCID collection for second SIM on Sierra Wireless and Quectel EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00		Ensure LTE band lock stays enabled on Hucom modules	5447
EM06 modules. Previously showing same ICCID for both SIMs Fix IP connectivity when using Huawei 709 with firmware 11.652.65.00.00 6076		Fix crash when LTE band retrieval for SIMCom fails	
Fix IP connectivity when using Huawei 709 with firmware 6076 11.652.65.00.00			5946
		Fix IP connectivity when using Huawei 709 with firmware	6076
			5755



	Fix packet corruption caused by too small buffer size in Quectel/Simcom driver when using QMAP	
	Fix RSRP and RSRQ values reported by Simcom 7070 module using ${\tt vam}_{\tt -a}$ diagnostic command	5383
	Fix SIM in/out handling for Quectel modules	
	Fix SIM switch on Quectel RM500Q mobile module	5863
	Fix SMS msgs not decoding on 3Ireland Jasper SIMs	5888
	Fix va_mobile failing to start when SMS is enabled and caller config section is missing caller name option	4507
	Fixes for Cellient CDMA module crashes while dormant	5760
	Removed reset of default bearer APN at startup	5775
	Set LTE attach bearer for Huawei ME909 to ensure attaching to configured APN rather than default APN as detected by the mobile module	5634
	Support custom name for mobile config section	5542
	Support LTE band limitation for Huawei ME909U module (firmware > 12.63x.x)	3310
Network	Fix static default route configuration using target 'default' and netmask 0.0.0.0	5942
	Fixed \$ character in interface password leading to password corruption	5434
NTP	Defer chrony server instances until UCI interface is up to avoid misleading chrony errors in syslog	5550
	Fix incorrect stratum served to local clients. Fixes issue where local NTP server was defaulting to stratum 10, overriding the stratum retrieved from the remote NTP server once the clock had synchronised. Stratum can still be forced though configuration of option stratum however this is not recommended.	5550
	Include new UTC time in syslog message when clock is stepped	5659
OpenVPN	Added support for key direction configuration	5762
·	web: services->openVPN->certificates->Key Direction	
	cli: openvpn.openvpn.key_direction	
ррр	Recover from connection stalling indefinitely when CHAP success message is lost in the network	4631
Radius	Support for Radius added to JKG family	
Radius/Taca	Support for Radius and TACACS added to JKG family	
SCEP	Support rsaes-oaep encryption for pkcs7 signedData password	5872
SFP	Fix interface failing to restart after network package restart	6079
SNMP	Fix MIB related issue running snmpd as dedicated unique user	4965
Strongswan	Decrease OCSP/CRL fetch timeout to 3 seconds from 10 seconds to avoid resource issues for multiple tunnels using CRL	5954
	Enable support for GCM encryption algorithm	5774
	Exclude password field from re-enrollment requests	5993
	Fix crash when verifying ECSDA signature	5633
	Fix IPSec tunnel operation when with waniface option present	



Send DELETE message from Ik	nloaded, verify fingerprint of the root (Ev2 delete task for initiator. Previously nated the IKE_SA without sending a when connected against another VA els with different interfaces of change to each module after et to unsupported value	5879 6052 5862 5616 4482
Send DELETE message from Ik when initiator, the router termi delete which led to problems w router in responder role. Support multiple FlexVPN tunn Syslog Fix changelog not recording firs initialisation Fix logging when conloglevel s	Ev2 delete task for initiator. Previously nated the IKE_SA without sending a then connected against another VA els with different interfaces at change to each module after et to unsupported value	5862 5616 4482
when initiator, the router terms delete which led to problems we router in responder role. Support multiple FlexVPN tunn Syslog Fix changelog not recording first initialisation Fix logging when conloglevel services.	els with different interfaces that change to each module after	5862 5616 4482
Syslog Fix changelog not recording first initialisation Fix logging when conloglevel s	et to unsupported value	5616
initialisation Fix logging when conloglevel s	et to unsupported value	4482
	··	
Suppress excessive kernel logg	jing on Dakota WiFi	
	 	5312
Add hotplug script debug loggicli: system.main.hotpluglog	ng option	5646
Added -M option to ping for mt cli: ping <ip_address> -M PMT</ip_address>	<i>,</i>	
models using Sierra Wireless W	nvironment in case of corruption on /P7600 series processor (GW1150, on where machtype could revert to	
Debrand web and command lir	ie interface	5498
Fix crash in in uci list comma	nd	5596
	es causing issues with telnet access	5333
TACACS Stpport for TACACS added to J	KG family	
Web/BGP Added BGP status page web: status->BGP		5819



Web/BGP	Added missing options to web UI	5817
	web: network->bgp->global settings->Maximum Dynamic Neighbours	5818
	<pre>cli: bgpd.routing.max_dynamic_neighbors</pre>	
	<pre>web: network->bgp->global settings->VRF</pre>	
	<pre>cli: bgpd.routing.vrf</pre>	
	<pre>web: network->bgp->bgp neighbours->BGP instance</pre>	
	cli: bgpd.peer.routing	
	web: network->bgp->bgp neighbours->Inbound Route Map	
	<pre>cli: bgpd.peer.inbound_route_map</pre>	
	web: network->bgp->bgp neighbours->Outbound Route Map	
	<pre>cli: bgpd.peer.outbound_route_map</pre>	
	web: network->bgp->bgp neighbours->EBGP Multihop	
	cli: bgpd.peer.ebgp_multihop	
	web: network->bgp->bgp neighbours->Inbound Soft Reconfiguration	
	<pre>cli: bgpd.peer.inbound_soft_reconf</pre>	
	web: network->bgp->bgp neighbours->Source Interface	
	cli: bgpd.peer.source	
	web: network->bgp->bgp neighbours->Password	
	cli: bgpd.peer.password	
	web: network->bgp->bgp neighbours group->BGP instance	
	li: bgpd.peer_group.routing	
	web: network->bgp->bgp neighbours group->network	
	<pre>cli: bgpd.peer_group.network web: network->bgp->bgp neighbours group->ASN cli: bgpd.peer_group.asn web: network->bgp->bgp neighbours group-Local Peer</pre>	
	cli: bgpd.peer_group.next_hop_self	
	web: network->bgp->bgp neighbours group->Holdtime	
	cli: bgpd.peer_group.holdtime_sec	
	web: network->bgp->bgp neighbours group->Keep-Alive Interval	
	cli: bgpd.peer_group.keepalive_sec	
Web/Event	Support for custom facility and target configuration options for syslog target	4739
System	web: services->va event system->event destination->Facility	
	<pre>cli: va_eventd.target.facility</pre>	
	web: services->va event system->event destination->Severity	
	<pre>cli: va_eventd.target.severity</pre>	
Web/IPsec	Support configuration for FlexVPN via web UI	6000
-	web: services->ipsec->connection->Route Interface	
	cli: strongswan.connection.route interface	
	web: services->ipsec->connection->FlexVPN Prefixes	
	cli: strongswan.connection.flexvpn_prefixes	
	Support configuration of local cort via web LII	6000
	Support configuration of local cert via web UI	6000
	web: services->ipsec->scep certificate->Local Certificate	
	cli: strongswan.connection.localcert	
Web/L2TP	Fix interface connect button for L2TP interfaces	5768
Web/Mobile IP	Fix web UI configuration when no configuration options exist in package dynamics	5787



Web/RADIU S	Add RADIUS and TACACS support to web UI web: system->system->PAM Authentication	5591
Web/SCEP	Support configuration of SCEP fingerprint and CA Name via wb UI web: services->ipsec->scep certificate->CA Fingerprint cli: strongswan.scep_cert->fingerprint web: services->ipsec->scep certificate->CA Name cli: strongswan.scep_cert->ca_name	6001
Web/SNMP	Fix web UI configuration when no configuration options exist in snmpd system and agent configuration sections	5786
Web/Status	Added VRF to routing table display web: status->active routes	
Web/WiFi	Allow selecting modulation mode for Qualcomm qcawifi drivers	5219
WiFi	Fix Dakota WiFi defaults to be more secure	4408
WiFi	Ignore WiFi type when only single WiFi supported by firmware to avoid issues with third party AP's	5905

10.11 Release 25.01.40.028

Module	Short Description	Mantis
Activator	Fix to correctly detect 'Software Up To Date' status from Activator	5481
DNS	Properly handle duplicate DNS entries on multiple interfaces	4993
Dropbear	Don't allow root to login if option RootLogin is disabled	5003
Ethernet	New automatic watchdog script to check switch MIB counters and reset if not incrementing on GW1042 hardware	3589 4423
Event System	Fix allocated memory boundaries violation with syslog target	5298
	Fix corrupted email target messages	5463
	Fix crash when SNMP target template length was multiple of 4 bytes	5460
	Fix intermittent memory management error	
	Increase event system target name length from 16 to 127 characters	5420
	Report system error when send fails due to session open failure	
	Use UDP port 162 by default for SNMP trap destination port	5435
Failsafe	Fix reboot command in failsafe mode	4885
GPS	Only try to get GPS coordinates for inventory collection when GPS	4905
	enabled to avoid unnecessary log messages	4919
HTTP Server	Added support for redirecting HTTP to HTTPS	4585
	web: services->http server->Redirect HTTP requests to HTTPS	
	cli: uhttpd.main.redirect_https	
ISAD	Add info on cell technology used for each bin	5159
LED	Power/Config led off now flashes slowly while the router is in recovery mode.	4510
Mobile	Add additional echo detection as an indication of radio module reset	5410
	Ensure mobile interfaces get a /32 netmask.	5173



	Ensure that roaming template generated multiwan interfaces are updated when va_mobile is restarted	5010
	Fix auto connect if mobile interface dropped during DST transition hour when moving from BST to GMT	5334
	Fix connectivity issues in PPP mode with some APNs due to dialled address in dial string	5314
	Fix fix signal strength reporting for Asiatel modules	5146
	Fix intermittent issue where route is not populated to routing table when mobile interface comes up on QMI interfaces	4847
	Fix parsing of special characters in mobile username and password	5070
	Fix Quectel EM06 GPS location	4940
	Fix SINR=-1 readings clearing out other mobile status values	4907
	Fixed bug in the reinitialisation of the QMI control code which led to a failure to detect the loss of connectivity and failures when trying to reestablish connectivity	5242
	Fixes so that we support IPv4, IPv4v6 and IPv6-only modes for PPP and QMI	4839
	Improve interface status detection for roaming templates interfaces	4988
	Improvements to detection and recovery of mobile module restart	5310
	Only poll temperature on SIMCom7100 modules that support it to	4914
	avoid signal quality monitoring not being enabled due to disabling of temperature monitoring	4916
	Report correct SIM slot after roaming scan	4987
	Support for new option ip6ifaceid for ability to set IPv6 suffix and add to received prefix to form full IPv6 address. cli: network.interface.ip6ifaceid	4840
	Use PDP context 3 for Quectel, Simcom and Sierra Wireless modules as the first data context. This fixes issues on Verizon networks where only context 3 can be used.	4921
Multiwan	Poison routes of managed interface after interface start so that routing is confirmed before redirecting traffic over it	5287
	Always configure 10 inteface with 127.0.0.1/8 address	4760
	Fix carrier check to only run for Ethernet interfaces	5409
	Prevent duplicate default route when using PPP mode for a mobile connection	5130
SCEP	Support for Cisco CA	4841
SNMP	Ensure that both specific field (SNMPv1) and snmpTrapOID (SNMPv2+) are set correctly.	5449
Strongswan	Don't reject certificates with invalid certificate policies. The certificate policy itself is still considered invalid and is not returned in the auth config resulting from trust chain operations.	5110
	Ensure all certs and keys are only writable by root and readable by strongswan	5161



	Fix crash in <code>ipsec statusall</code> output parser when lua pattern magic characters are used. Fixes issue with IPsec status web UI page not displaying when using the minus symbol '-' in policy names.	4901
	Fix crash when responding to connection initiation when NATT disabled	5293
Syslog	Frequent upnp messages in syslog no longer generated	5160
System	Avoid overwriting <code>/dev/null</code> with newly created config file when configuration audit is enabled	5080
	Ensure /etc/systime is updated upon reboot command issued from Activator	5297
USB	Fix USB intermittently changing serial port mapping after reboot by introduction of new option for mapping a user-friendly serial port name to the underlying linux device name. See new features section above. cli: tservd.port.serialPortName	5107
VA Events	Correct wrong parameter order in BadPasswordSSH event default template	4849
	Fix cwatch vaevent generation	4904
Web/Firewall	Fix issue in port-forward rule creation via web UI	4872
Web/Flash Operations	Improve hash checking of firmware upgrade via web UI	4984
Web/System	Added configuration of luci login template information to web UI web: system->system-general settings->Login info template cli: luci.main.login page_info template	3791
	uImage with appended uboot now updates correctly via the web	5006
Web/WiFi	Allow configuration of modulation mode	5219
WiFi	Support for option to hide SSID web: network->wifi->interface configuration->Hide ESSID cli: wireless.wifi-iface.hidden	5375

Note: Changes for releases prior to CPX-25.01.43.028 have been archived