

Document

## Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

# WeOS 5.27.0

## Release Notes

### Contents

1	Summary of Changes	5
1.1	News in 5.27.0	5
1.1.1	Improved audit-log viewing and pager handling in CLI	5
1.1.2	CLI media context enhancements	5
1.1.3	SNMP Trap Hosts via FQDN	6
1.1.4	PTP Boundary Clock for Lynx-5xxx, RedFox-5xxx, and RedFox-7xxx	6
1.1.5	Mroute entries extended from 128 to 256 and group ranges supported	6
1.1.6	WireGuard	6
1.1.7	SNMP dot1dTpFdb table	6
2	Fixed Issues	7
2.1	WeOS 5.27.0	7
3	Known Limitations	10
3.1	Ring Coupling version 2 not supported	10
3.2	Port Access Control	10
3.3	RMON	10
3.4	Login	10
3.5	Setting Date Manually	11
3.6	Available ports for boot specific functionality	11
3.7	Routing Hardware Offloading	11
3.8	Redundancy protocols on Relay ports	12
3.9	FRNT	12
3.10	RSTP	12
3.11	IEC 61375	12
3.12	Custom TRDP telegrams	13
3.13	LLDP	13
3.14	Port Monitoring	14
3.14.1	Cross switch core limitation	14
3.15	Media Redundancy Protocol (MRP)	14

Document

Release Notes WeOS 5.27.0

Date  
December 16, 2025

Document No  
224004-g0e717d2

3.16 10G SFP Ports . . . . .	14
3.17 Search function in User Guide . . . . .	15
3.18 RedBox PTP Boundary Clock . . . . .	15
3.19 Ingress rate limiting . . . . .	15
3.20 Policy Traffic Filtering . . . . .	15
3.21 Static unicast MAC filters for link aggregates . . . . .	15
4 Known Issues . . . . .	16
4.1 List of known issues . . . . .	16
4.2 #20888 & #20868 Redfox and Lynx 5000 1Gbps SFP issues . . . . .	20
4.3 #18163: Work-around for OSPF NSSAs convergence issue . . . . .	20
5 Quick Start Guide . . . . .	21
5.1 Default User and Password . . . . .	21
5.2 General . . . . .	21
5.3 CLI . . . . .	22
6 Firmware Upgrade . . . . .	24
6.1 WeOS Image . . . . .	24
6.2 Boot Loader . . . . .	24
7 Significant differences between WeOS 4 and WeOS 5 . . . . .	25



Document Release Notes WeOS 5.27.0	
Date December 16, 2025	Document No 224004-g0e717d2

## Legal Information

The contents of this document are provided “as is”. Except as required by applicable law, no warranties of any kind, either express or implied, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose, are made in relation to the accuracy and reliability or contents of this document. Westermo reserves the right to revise this document or withdraw it at any time without prior notice. Under no circumstances shall Westermo be responsible for any loss of data or income or any special, incidental, and consequential or indirect damages howsoever caused.

More information about Westermo at <http://www.westermo.com>

Document	
Release Notes WeOS 5.27.0	
Date	Document No
December 16, 2025	224004-g0e717d2

## Important User Information

This section details important user information, directed in particular to new users of WeOS 5:

For help with getting started using WeOS 5, refer to the Quick Start Guide in section 5.

### User Guide

In WeOS 5, the primary user documentation is referred to as the WeOS 5 *User Guide*. Compared to the WeOS 4 *Management Guide*, the User Guide is a web first publication focusing on use-cases, documented in stand-alone “HowTo:s”, and configuration guides for all supported sub-systems.

The User Guide is included in the release Zip file in the sub-directory: doc/weos/user-guide/. To access the documentation, open the following file in your web browser:

`file:///Downloads/WeOS-5.27.0/doc/weos/user-guide/index.html`

The *User Guide* is also available online at <https://docs.westermo.com/weos/weos-5/>.

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

## 1 Summary of Changes

This section details new features added in this minor release.

Users new to WeOS 5 are recommended to read section 7 carefully, as it high-lights some of the major differences between WeOS 4 and WeOS 5.

### 1.1 News in 5.27.0

The subsection below describe news in WeOS 5.27.0. In addition, section 2.1 includes information on fixed issues.

#### 1.1.1 Improved audit-log viewing and pager handling in CLI

The CLI pager and the audit display have been improved to make it easier and safer to inspect long audit logs directly from the device. The key changes are:

- **Exit keys:** It is now possible to exit the interactive pager using `Ctrl-C` or `Enter` in addition to the existing `q` key, making it quicker to return to the prompt.
- **Show-all:** A new pager key has been added to display the entire content without paging. When used while viewing the audit, the full audit log will be presented without further pagination.
- **Robustness:** The pager has been refactored to avoid queuing large amounts of fast key presses (for example when a key is held down), which previously could lock the pager for an extended time on console sessions.

In addition, the `show audit` handling has been improved for cases where the interactive pager cannot be used (for example when the terminal window is too small or the CLI is running in non-interactive mode).

#### 1.1.2 CLI media context enhancements

The media context in the CLI has been extended with a small set of user commands to make manual control of external media easier. The new commands allow an administrator to eject (unmount) a recognised media definition (optionally forcing the operation), and to mount media that are currently listed as *inactive* or *available* without physically reconnecting the device.

These commands operate only on media definitions known to the boot configuration and do not change the existing access-control or hotplug behaviour. Typical uses include re-mounting media that were intentionally ejected, or recovering from transient mount failures where a device did not automatically mount. For normal operation hotplug will continue to be the recommended mechanism for media mounting.

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

### 1.1.3 SNMP Trap Hosts via FQDN

SNMP Trap Hosts can now be configured using FQDN instead of only IP addresses.

### 1.1.4 PTP Boundary Clock for Lynx-5xxx, RedFox-5xxx, and RedFox-7xxx

PTP Boundary Clock is now supported on the product series Lynx-5xxx, RedFox-5xxx, and RedFox-7xxx.

For more information see the WeOS User Guide section *Configuration Guides* → *Network Services* → *PTP/IEEE 1588*.

### 1.1.5 Mroute entries extended from 128 to 256 and group ranges supported

Mroute entries have been extended from 128 to 256 entries. In addition, it is now possible to configure mroute entries using group ranges.

For more information see the WeOS User Guide section *Configuration Guides* → *Routing* → *Multicast Routing*.

### 1.1.6 WireGuard

Support for WireGuard VPN has been added. WireGuard is a modern, fast, and secure VPN protocol designed to be simpler and more performant than traditional VPN solutions like IPsec and OpenVPN. WeOS includes WireGuard support to provide efficient and secure VPN tunnel services.

For more information see the WeOS User Guide section *Configuration Guides* → *Tunnels and VPN* → *WireGuard*.

### 1.1.7 SNMP dot1dTpFdb table

SNMP dot1dTpFdb table is now supported. If the same MAC is present in more than one VLAN, it's recommended to use the dot1qTpFdb table because each VLAN will have its own table there.

## 2 Fixed Issues

### 2.1 WeOS 5.27.0

Fixed issues in WeOS 5.27.0 (as relative to 5.26).

Issue	Category	Description
#20859	FRNT	Long fail-over times when rebooting FRNTv2 member switch
#20821	Alarm	Pre 5.26 configuration for FRNT alarm will incorrectly load "active-low" parameter
#20815	VLAN	Device ignores configuration setting for disabled vlan after reboot
#20782	VPN	IPsec : All ipsec running config disappears when creating new initiator in WebGUI
#20781	System	Float values are not validated correctly by configuration input validation
#20777	PTP	Retrieving details regarding a specific clock ID, queries all PTP nodes
#20776	PTP	Not possible to set PTP version
#20766	Policy	Policy Traffic Filter edit in webUI changes port
#20758	TCN	IP-TCN instability when system is loaded with SNMP request for TTDP data under certain conditions
#20754	Link Aggregation	Static unicast fdb filters for lags have no effect on Viper 3000 and Lynx 3000
#20736	System	CPU does not prioritize FRNT management traffic on Redfox and Lynx 5000
#20694	VPN	IPsec Unable to change Role from Initiator to Responder
#20693	WEB	DHCP-relay webpage does not return errors if validation error occurs
#20690	System	System crash with reboot after multiple hours when running "repeat show logging"
#20653	System	Executing show FDB over SSH towards Redfox and lynx 5000 devices breaks FRNT ring in special circumstances
#20649	Alarm	Interval is not saved to config file for Trigger types Media and Media-Threshold
#20633	RSTP	SNMP service not responding causes RSTP to storm
#20623	VPN	IPsec : The status box for the IPsec tunnel is always empty
#20622	VPN	IPsec : Web shows different status than CLI
#20613	PTP	Viewing PTP Status in WEB may crash PTP daemon
#20595	System	No audit log message when setting date & time manually

Continued on next page

Document Release Notes WeOS 5.27.0	
Date December 16, 2025	Document No 224004-g0e717d2

Continued from previous page		
Issue	Category	Description
#20569	TCN	comID-131 field etbnRole loses state for not redundant setups after first request
#20548	WEB	Setting password in Encrypted Secrets in WEB doesn't work
#20528	AAA	Downgrade of factory reset device could force the device to enter failsafe mode
#20517	CLI	'erase' command tab-completion is handled different depending on context
#20513	QoS	Rate limit limits to about half of the value set on egress for Viper-3000
#20507	QoS	Rate limit on egress does not limit on switchcore 0
#20505	AAA	Error message 'Could not delete file <cert-name>' appears when importing new pki certificate
#20483	VPN	SSL interface has "(null)" option as cipher in Web
#20481	Logging	show logfile does not generate an audit event
#20478	WEB	Configuring Local User DB doesn't work
#20475	VLAN	FDB entries are not correctly cleared when VLANs are removed
#20416	SNMP	SNMP Read and Write community can not be same as that blocks Write function
#20302	WEB	WEB status for TCN missing most data
#20274	Alarm	Entering the severity command with unknown option will crash clish
#20246	Alarm	Route Monitor doesn't reset the admin distance to the configured value if an alarm triggered
#20245	VPN	IPsec tunnel can be established with wrong PSK in special circumstances
#20221	DHCP	DHCP snooping not limiting to defined VLAN and snoop up all port 67 request
#20220	WEB	Impossible to set peer as a DNS name in SSL client tunnel
#20216	WEB	Cipher cannot be set via WebGUI in the Open VPN settings
#20067	DHCP	DHCP server send out empty option 121/249 fields to clients not requesting the options if set on any static lease
#20010	General	Metrics - Cannot access the web port using IPv6 address
#19998	General	Metrics on ports not working on Dagger Lynx 5512
#19991	DHCP	Disabling Gateway setting in 'Server-setting' breaks Inherit Gateway in 'Subnet-setting'

Continued on next page

Document Release Notes WeOS 5.27.0	
Date December 16, 2025	Document No 224004-g0e717d2

Continued from previous page		
Issue	Category	Description
#19977	CLI	Custom SNMP engine-id length is not enforced in CLI configuration
#19947	System	IPv6 SCP not working (copy, upgrade)
#19850	PTP	Different link speeds causes higher TC error rate
#19692	Firewall	TCP port 53 listening when DNS server functionality disabled.
#19524	WEB	Unable to delete VLAN by WEB when FRNT is enabled (Lynx 3000, 5000 and Redfox)
#19024	Link Aggregation	Using link-aggregates as FRNT ring ports gives long failover times in ring topology changes
#18808	Alarm	Link-alarm with multiple ports makes status-relay indicate OK when some port is up and others down
#18643	PTP	RedFox 5528/5728 fiber ports (Eth1-4) have more jitter in the correction field accuracy than the other fiber ports

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

### 3 Known Limitations

This section describes known limitations in WeOS.

#### 3.1 Ring Coupling version 2 not supported

Support for FRNT Ring Coupling (RiCo) version 2 was removed in 5.15.0 due to problems with the stability of the function. Most of the use cases for RiCo version 2 can be covered today through the use of FRNTv2 and RiCo v3.

For information around FRNT v2 and RiCo v3 usage please contact local Westermo support.

#### 3.2 Port Access Control (IEEE 802.1X and MAC Authentication)

Wake-on-LAN is currently not possible on controlled ports. The reason is that broadcast traffic is not allowed to egress a controlled port until there is at least one MAC address authenticated on the port.

#### 3.3 RMON

Some Hardware platforms are unable to provide certain RMON counters due to problems with the hardware chipset.

- RCV Error counter does not work on Viper 3512 and 3520
- FC Received (rx\_pause) does not work on Lynx 5000 and Redfox

#### 3.4 Login

Known limitations related to the Login service.

##### Side-effect of disabling console login

When disabling login from console, login via telnet is also prohibited (even when telnet login is enabled).

##### SSH Public Key Lost When Disabling Built-in User

WeOS 5.13.0 introduces support for importing SSH public key for built-in users, as well as the ability to enable/disable a user. When disabling a user, the intention is that the user shall be prohibited from logging in, while other user configuration is till kept in the configuration file.

However, the disabling of a user currently implies that any SSH public key associated with the user is removed and needs to be imported again upon enabling the user.

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

### 3.5 Setting Date Manually

Setting a manual date on the WeOS unit before 1 January 2000 will render an error message.

### 3.6 Available ports for boot specific functionality

The boot loader rescue mode only supports regular copper ports, not SFP ports. On RedFox-5528, ports 1-4 are also not supported until the system has booted.

### 3.7 Routing Hardware Offloading

The routing Hardware Offloading support for Viper-TBN introduced in WeOS 5.8 has shown to have instabilities. In particular, when used with dynamic routing, there are issues not yet solved. Therefore hardware offloading has temporarily been Disabled by default.

```
viper:/#> configure
viper:/config/#> ip
viper:/config/ip/#> offload
viper:/config/ip/#> leave
```

When Offloading is Enabled, regular IPv4 forwarding is handled in hardware with some exceptions, see the WeOS 5 User Manual for details (section 'Configuration Guides'/'Routing'/'Offloading').

For Redfox and Lynx-5000 initial Offloading support in 5.23.0. Functionality only cover a very small subset of use cases yet and has a list of restrictions.

The Known limitations for offloading on Redfox and Lynx-5000:

- Routed IPv6 traffic is handled by the CPU
- IP multicast traffic will be routed by the CPU
- Firewall forwarding chain will not impact any routed Unicast traffic
- NAT will not be performed on any routed traffic
- Only VLAN interfaces can be used, usage of Port-interfaces will not perform any traffic forwarding
- Policy-Based Routing will not function
- SSL-tunnel will function to some extent via the CPU but is strongly discouraged from being used in this release

Tracking vrrp instances with mroutes is not supported when offloading is enabled. If this feature is used it is recommended to disable offloading. (opposite steps to the example above).

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

Use of the WeOS Firewall together Hardware Offloading is not supported and the behaviour of doing so is undefined. The exception is when firewall configuration is limited to *filter input* rules.

Hence, if the Firewall is used to configure *filter forwarding* rules, *NAPT* rules or *port forwarding* rules on a Viper-TBN, it is necessary to disable the Hardware Offloading (opposite steps to the example above).

```
viper:/#> configure
viper:/config/#> ip
viper:/config/ip/#> no offload
viper:/config/ip/#> leave
viper:/#>
```

### 3.8 Redundancy protocols on Relay ports

It is only supported to run link-aggregation as the selected option for redundancy on Relay ports. This is due to the fact that any other protocol can end up in very uncertain situations in cases where the bypass-relays are used.

In the future WeOS may refuse enabling these protocols on relay ports.

### 3.9 FRNT

Fastlink must be enabled manually for FRNT (gigabit Ethernet) ring ports.

Fastlink is a unique feature of Westermo products to optimise gigabit Ethernet link-down fail-over times in layer-2 redundancy protocols such as FRNT.

### 3.10 RSTP

WeOS 5 supports RSTP, compliant to IEEE 802.1D-2004. Due to limitations in the WeOS 4 implementation of RSTP, a WeOS 4 unit will keep ports in blocking mode longer than needed when connected to a WeOS 5 node.

Hence, mixing WeOS 4 and WeOS 5 units in RSTP topologies may exhibit relatively long periods with limited connectivity during topology changes, this applies to both link failure and when a link comes up again.

Link aggregate path-cost use the configured port speed value(s) and not the negotiated speed value. This can lead to RSTP making the non-optimal path selection. Work-around this issue by setting a fixed path-cost in the spanning-tree port configuration.

### 3.11 IEC 61375

In this release, not all of the recovery use cases, nor the optional cases, are supported.

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

TTDP and non-TTDP multicast can be used simultaneously in this release, but is considered unstable and is strongly recommended to be avoided.

"Automatic Gap Insertions", when several vehicles have the same name, can lead to unexpected behaviour.

When recovery-mode is set to deferred/wait, an ECSC must be running on the configured multicast address. If no ECSC is running and sending data on the configured multicast address, no node will come up at all.

It is strongly recommended to enable inauguration inhibition on all nodes to reduce spurious re-inaugurations and guarantee a stable train communication.

The "ECSP inhibit sync" function should only be enabled in consists with simple or straightforward ECN configurations. In complex configurations with non-symmetric ETBN/ECN connections and/or configurations where different ETBNs are master routers for different ECNs simultaneously, the backup ETBNs will not be able to unambiguously determine which ETBN is the master router/ECSP, which can in turn lead to unexpected behaviour with regards to the local inauguration inhibition value. In these cases, manually setting the local inauguration inhibition values on the backup ETBNs, via the ETBN\_CTRL telegram, should instead be performed.

VRRP virtual IP address ("VIP") is primarily intended to be used as a gateway/router address, and not as a host address. However, using the VIP as a host address, that at any one time belongs to the currently active ECSP is a common use case. When using the VIP in this way, for ECSC-ECSP communication, it is recommended that the "vmac" option in the VRRP configuration be turned off for all VRRP instance whose VIPs are used in this way.

### 3.12 Custom TRDP telegrams

The implementation of Custom TRDP telegrams has some limitations:

- The Custom TRDP telegrams feature is only available if the TTDP (IP-TCN) operational mode is either **full** or **off**. It is currently not supported in **etbn-only** mode.
- Data from up to 32 device ports can be included across all defined datasets.
- Data from up to 8 VLANs can be included across all defined datasets.
- Data from up to 4 FRNTv2 rings can be included across all defined datasets. FRNTv2 is the only supported ring protocol for which data can be included.

### 3.13 LLDP

When using Link Aggregation, the individual member ports will transmit LLDP frames using the MAC address of the link aggregation interface, i.e. all member links in an aggregate will be using the same

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

MAC address.

### 3.14 Port Monitoring

It is not possible to utilise port monitoring directly on a link aggregation port interface. However it is still fully possible to monitor the individual member ports that constitute any given link aggregate.

Therefore, in order to fully monitor an aggregate, monitoring must be configured for each of the aggregate member ports.

#### 3.14.1 Cross switch core limitation

It is not possible to use port-monitor where the source and destination ports are split between switchcore 2 and 3 on Viper-120 and Viper-220 products.

Having the source and Destination port on the same switch core or one of the source or destination ports on ports ethX7, ethX8, ethX14 or ethX20 while the other resides on one of the other switchcores is possible.

### 3.15 Media Redundancy Protocol (MRP)

- *MRM not supported for MRP 30 profile:* WeOS 5 units can be configured to operate in MRP 200 or MRP 30 profile. However, for MRP 30 profile, configuring the WeOS 5 unit as MRP Master (MRM) is not supported. A WeOS 5 unit can be used as MRP Client (MRC) with MRP 30 profile with MRMs from other vendors.

More details: When a link comes up between two MRP clients, the clients send *link-up* messages to the MRP master. The MRP 30 ms profile only gives the MRP master 4 ms to block its secondary port from the time the MRP clients send their first *link-up* message. The WeOS 5 MRP Master is not always capable of doing that, resulting in a short transient loop in the MRP ring when the ring is healed.

To avoid this, it is recommended to use the MRP 200 ms profile instead. For link-down scenarios, MRP 200 ms profile conducts failover as fast as the 30 ms profile, given that MRCs in the ring are capable of sending MRP *link-down* messages (WeOS units have this capability).

- *Use of MRP with virtual L2 ports (SSL VPN ports):* MRP is specified for use with Ethernet ports (full duplex, 100 Mbit/s or higher). WeOS enables the use of running MRP over SSL L2 VPNs, but requires the VPN to run over a high-performance network to work well. Furthermore, only the MRP '200 profile' can be used with SSL VPNs.

### 3.16 10G SFP Ports

The 10G SFP ports on RedFox-7528 have the following limitations:

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

- IEEE 1588/PTP is currently not supported on 10G SFP ports.
- 10G SFP ports are only to be used for 10G Fiber SFPs or 1G Fiber SFPs, not copper SFPs or 100 Mbit/s Fiber SFPs.
- Status of MDI/MDIX and polarity shows value 'Invalid' ('N/A' or 'Not Applicable' would be more appropriate).

### **3.17 Search function in User Guide**

The User Guide included within the release-zip is Web based. The Search function in the User Guide navigation pane only works if you make the pages available via a Web Server. That is, the Search function does not work when opening the User Guide via your local file system.

At <https://docs.westermo.com/weos/weos-5/> you can browse the WeOS 5 User Guide online, with Search function included.

### **3.18 RedBox PTP Boundary Clock**

RedBoxes running Boundary Clock in an HSR ring must be connected with all A ports in the same direction. As the BC prioritizes synchronizing from the A port, if two BC are synchronizing towards each other neither of them may end up in a stable state.

Connect devices as shown below:

```
ethA-RB-ethB <-> ethA-RB-ethB <-> ethA-RB-ethB ....
```

### **3.19 Ingress rate limiting**

On Viper-3000 series and Lynx-3000 series, ingress rate limiting of multicast traffic includes broadcast.

### **3.20 Policy Traffic Filtering**

For Redfox 7000/5000 and Lynx 5000-series, policy traffic filtering counters are not functional for drop filters and are therefore not displayed.

### **3.21 Static unicast MAC filters for link aggregates**

Static unicast FDB filters are known to not work as expected when the port associated with the filter is a link aggregate that spans multiple switch cores.

## 4 Known Issues

### 4.1 List of known issues

Issue	Category	Description
#20897	System	The system fails to read a valid Policy Traffic Filtering running configuration after a reboot
#20896	Any	mDNS discovery not working on Redbox
#20894	WEB	The DHCP option 12 and do not allow FQDN to be set via WEB but is allowed in CLI and according validation schema
#20892	Policy	It is not possible to drop 224.0.0.0/24 traffic from reaching the switch CPU
#20891	Kernel	Port priority does not work across switchcores (DSA)
#20888	Ports	Redfox and Lynx 5000 SFP handler can fail to setup the correct low level duplex settings for Gbps SFPs
#20887	System	SCEP : an RA-cert with the CA:True flag set is not recognized as RA
#20886	MRP	EC-62439-2-MIB Do Not Count Up
#20868	System	Ports Eth1-Eth4 on Redfox can become unable to transmit packets after sustained CPU routing overload
#20865	FRNT	FRNT traffic disappears and FRNT is unhappy when using Dagger.
#20853	FRNT	Recovering a FRNT ring disturbs other subring/s or the opposite
#20835	Ports	Port priority can't handle change or reboot
#20833	System	Buffer overflow via crafted input leading to denial of service
#20831	AAA	IPSec ESP cipher authentication value does not match the CLI/config settings
#20828	System	Deactivating Watchdog in Lynx + RedFox 5000 & 7000 series reboots the unit continuously
#20826	VPN	Dpd timeout treated as constant in schema and not written to strongswan configuration file (only applicable for IKEv1)
#20822	Alarm	Configuring RING alarms from WEB results in wrong active mode (condition)
#20820	WEB	Web becomes unusable when an upgrade was aborted or done without a reboot
#20816	Firewall	Neither input nor forward rules can have "ANY" as interface
#20779	System	Metrics process causes high CPU load and affects FRNT ports
#20771	WEB	WEB page is sporadically not updated after configuration
#20752	General	PKI : only first certificate in a bundled visible

Continued on next page

Document Release Notes WeOS 5.27.0	
Date December 16, 2025	Document No 224004-g0e717d2

Continued from previous page		
Issue	Category	Description
#20749	TCN	TCN can fail to build TTDB properly in the extremity 2 backup TBN when cstinfo have same cstID and/or vehID
#20748	System	RMON does not show Filtered/Discarded values
#20737	VRRP	VRRP do not consider vrrp-startup-delay at bootup if another vrrp device is active and spam logfile with bad entries
#20733	Firewall	Port forwarding can not handle other protocols than TCP and UDP
#20724	WEB	Rich is an extended functionality in web and non extended functionality in weos
#20712	TCN	ETBN bypass relay control not working in comID 130
#20703	VLAN	Incorrect ARP requests sent when bridging LAGs on Redfox and Lynx 5000
#20662	Any	no boot does not reset allow-untrusted/unlock-license
#20658	VRRP	Multicast routing intermittent perpetual failure during VRRP failover with preemption
#20627	Port Access Control	Inconsistent and delay in MAC Address Authentication
#20617	VLAN	Packets seen on different VLAN in specific circumstances
#20603	System	Upgrade command can hang device forever in runlevel 9
#20578	NTP	RTC may lock at wrong time at power down if backwards time jump has happened
#20574	Logging	Excessive logging during configuration change
#20571	System	Active SSH sessions not closed when a config restore is done via WEB allowing password manipulation in file afterwards
#20533	SNMP	Wrong values in the "ttdpSubnetIPMask" OID answers, the MIB returns 255.255.252.0 (/22), but shall displays 255.255.192.0 (/18)
#20526	Alarm	Unexpected errors and behaviors during selecting of iface as target in action via both webGUI and CLI
#20515	TCN	teamd spam logfile at start of device
#20509	WEB	PKI - Enrollment Servers configuration page does not have a Help webpage
#20410	DHCP	Unable to bind IP address when short DHCP leasetime is provided
#20312	AAA	Possible to get locked out if lockout policy is set and no valid connection to Radius server
#20309	System	Firmware upgrade could reset the user password
#20281	System	The error message "Failed to add audit entry to audit daemon" is spammed when applying large configs.

Continued on next page

Document Release Notes WeOS 5.27.0	
Date December 16, 2025	Document No 224004-g0e717d2

Continued from previous page		
Issue	Category	Description
#20249	System	Defensics: Repeated connections to telnet may cause a DoS condition on telnet service
#20233	HW	RTC: System time might not be stored correctly
#20231	WEB	Fail with restoring config in WEB but no fault messages
#20201	System	Rebooting after disabling offloading will remove all traffic policies
#20150	System	DHCP Reply seems to be offloaded, cannot accept address
#20144	Alarm	Ping Alarm indicates UNREACHABLE when the destination is reachable
#20127	System	Metricsd can cause leak memory
#20102	SNMP	SNMP value for frntStatusVid1/2 show no data in tables
#20091	Link Aggregation	LACP Removal of lag when custom fdb filters referenced to the lag fails assertion of the running-config file
#20047	WEB	The user is redirected to the login page when editing firewall rules is tried
#20045	LED	After initiating a 'factory reset' from the web GUI, a device will boot up, but the ON LED will remain RED even when boot is com
#20040	Any	When IP address is changed from CLI, a gratuitous ARP is send with the old IP instead of new one
#19965	WEB	FRNTv2 is not shown in Status summary page when it is enabled
#19958	Boot Loader	Envoy Barebox uses precompiled ATF
#19957	General	Port statistics not available on Redfox and Lynx 5000
#19928	TCN	Offloading with TCN does not allow for fragmented packets to be forwarded
#19925	System	Configuration Hash does not get generated after factory reset
#19924	VRRP	VRRP instance is not restarted when doing a config restore on Vipers
#19903	System	configuration restore do not clear previous added route from system
#19882	System	Upgrade from ftp sever with DNS name does not work
#19880	WEB	Refreshing page when upgrade of bootloader or secondary restarts the upgrade if it's done
#19878	CLI	Config abort do not work correctly with an invalid configuration
#19870	IGMP	Multicast Snooping Boundary for MLD does not work on Dagger based systems.
#19826	System	Large amount of authenticated SSH sessions causes denial-of-service condition

Document Release Notes WeOS 5.27.0	
Date December 16, 2025	Document No 224004-g0e717d2

Continued from previous page		
Issue	Category	Description
#19818	SNMP	Syntax errors in Westermo MIB files for FRNT and EVENT
#19777	WEB	Upgrading primary image from web ui does not report flashing done in http response
#19760	WEB	WebGUI Vulnerability - cross-site request forgery
#19756	VRRP	The vmac of VRRP causes strange log messages and VRRP not to work properly
#19711	WEB	Cannot access help in some menus in webGUI when browser tree menu has gone past the bottom of the screen
#19575	IP Multicast	no multicast-snooping does not disable IGMP snooping
#19517	Logging	When PoE-chip goes repetitively down many Kernel logs is generated and stored
#19498	IGMP	Duplicate multicast packets over link-aggregates when changing router timeout (Dagger)
#19410	IGMP	Missmatch between MDB and ATU for mc group 239.193.0.1 when etbn is acting as router, sender and consumer of data.
#19323	FRNT	FRNT Focal point Topology Counter rush with LACP links (Dagger)
#19288	FRNT	After configuring FRNTv2 on Coronet/Viper 20A the FRNT leds are flashing red
#19262	Ports	Traffic not handled on Envoy ports using Copper SFPs
#19255	QoS	Priority-mode IP fails when both ingress and egress ports are fiber ports on Envoy platform
#19251	PoE	Lynx 3510 PoE leds continuously blinking in case of LV supply
#19181	Ports	Port-Priority-mode IP and Offloading broken with DSCP set field
#18967	System	Joins on SSL ports does not lead to the CPU port being added to the ATU
#18886	IP Multicast	Static multicast route with wildcard source fails to forward when group first heard on other interface
#18675	Link Aggregation	Long failover time (aggregate member link up/down) in link-aggregate interoperability case (WeOS5 'Dagger' vs WeOS4)
#18638	CLI	CLI does not allow "?" when configuring local user accounts password using clear-text
#18614	TCN	TTDP NAT rules incorrectly modifies packets between local CNs
#18362	TCN	Broken/missing ECSPs in train composition handled incorrectly
#18163	OSPF	Routes to 'redistributed connected E1 routes' lost within NSSA areas upon topology change

Continued on next page

Document	Document No
Release Notes WeOS 5.27.0	224004-g0e717d2

Continued from previous page		
Issue	Category	Description
#18151	Logging	Long-running programs log events to syslog with the wrong time stamp on timezone changes
#18076	MRP	Probing MRP status (30 ms profile) during heavy load may cause reboot (Viper-TBN)
#18069	QoS	ARP packets treated with lowest priority and may be missed/dropped under load
#17995	System	Service discovery not available in safe-config

## 4.2 #20888 & #20868 Redfox and Lynx 5000 1Gbps SFP issues

The port will operate in half-duplex mode when using a 1 Gigabit SFP module that is hot plugged into a gigabit SFP slot on Redfox 5000 or Lynx 5000 or when a 1 Gigabit SFP module is used in any SFP+ slot on Redfox 7000. Also note that the port may become unable to transmit frames over that port after sustained device overload until the port is reset.

#### 4.3 #18163: Work-around for OSPF NSSAs convergence issue

When using OSPF Not-So-Stubby Areas (NSSAs), failover when a router goes down may take a lot longer time than expected. There are two possible work-arounds until this bug is fixed:

- Alternative 1: Let each router get an address on its loopback interface, and include them in the OSPF area, e.g., use OSPF setting “network 192.168.1.5/32 area 1” for a router in (NSSA) area 1 with address 192.168.1.5/32 assigned to its loopback interface (lo).
- Alternative 2: Use ‘regular’ OSPF areas instead of NSSA areas.

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

## 5 Quick Start Guide

WeOS 5 devices are intended to be usable out-of-the-box as a switch. All access ports are assigned to the same VLAN (untagged) and the device tries to acquire a management IP address via DHCP. It also acquires a link-local address (in the 169.254.x.x range). These addresses are advertised with mDNS (Linux/Apple), SSDP (Windows), and LLDP.

### 5.1 Default User and Password

**user:** admin

**password:** admin

### 5.2 General

Apple, Linux, and Windows users with mDNS installed, can either use an mDNS client to find the device's IP address, or connect using a web browser:

- <http://weos.local>
- <http://redfox-4d-3b-20.local>

The first example is not available if there are many WeOS devices on the same LAN. The latter, and more reliable address, is a combination of the hostname and the last three octets of the device's MAC address in that LAN. In this example the hostname is `redfox` and the MAC address is `00:07:7c:4d:3b:20`.

Windows users without mDNS have SSDP to discover WeOS devices. In Windows 7 there is the *Network and Sharing Center* where a clickable icon for each discovered WeOS device should appear under *Network Infrastructure*. The PC must, however, be in the same subnet (DHCP or link-local) for this to work. Windows users also have the Westermo WeConfig tool to manage their WeOS devices.

Expert users can also use nmap, a port scanner, to scan the network for the device. Be aware though that this might be frowned upon should your device be located on a shared network.

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

## 5.3 CLI

WeOS comes with a Command Line Interface (CLI) that can be accessed via a console port at 115200@8N1, or Secure Shell (SSH). Only SSH protocol version 2 is supported. To gain access to the CLI using SSH you need:

- An SSH client, see below
- The device's IP address or DNS/mDNS name, see above
- The user name and password, default user: admin, password: admin

### SSH Clients

There are many of SSH clients available, some of them can even be used to connect to the devices using a (USB) serial console port. A few free clients are listed below. Please follow the directions for installation and usage applicable to your operating system and client.

**UNIX, Linux, Apple macOS** OpenSSH, <https://www.openssh.com>

**Apple macOS** Termius, <https://www.terminus.com>

**Windows** PuTTY, <https://www.chiark.greenend.org.uk/~sgtatham/putty/>

### CLI Overview

The CLI has two main scopes: admin-exec and configure context. The former is what the user lands in after initial login.

```
redfox-4d-3b-20 login: admin
Password: *****

.
.
.
| | | | -__|__ --|__ _ _| -__| _| . . | _| http://www.westermo.com
\__/\__/\___._____| |__| |____|_| |__|_| |_____| info@westermo.se
  Robust Industrial Data Communications -- Made Easy

\\ Westermo WeOS v5.3 5.3.x-g7890bde -- Oct 24 19:30 CEST 2018
Type: 'help' for help with commands, 'exit' to logout or leave a context.
```

```
redfox-4d-3b-20:/#> help
```

Central concepts in WeOS are: ports, VLANs, and interfaces. To see status of each in admin-exec context, use `show ports`, `show vlans`, and `show ifaces`.

To change settings, enter the configuration context with the command `config`. The same commands as above also apply here, but now display the configured settings. Notice how the CLI prompt changes to show the current scope.

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

```
redfox-4d-3b-20:/config/#> iface vlan2
```

To show or change the interface and VLAN properties the user enters the command: `iface vlan2` and `vlan 2`, respectively, with an optional “show” as prefix. E.g. `show iface vlan2`.

```
redfox-4d-3b-20:/config/iface-vlan2#> help inet
```

The help command is always available. Use it stand-alone or with a context-specific setting to get more detailed help.

To leave a level use the command `end` to save or `abort` (or Control-D) to cancel. To save and exit all levels, and go back to admin-exec, use `leave` (or Control-Z).

```
redfox-4d-3b-20:/config/iface-vlan2#> leave
```

Applying configuration.

Configuration activated. Remember "copy run start" to save to flash (NVRAM) .

The CLI, unlike the WebUI and WeConfig, has a concept of a running configuration. This is an activated but volatile (RAM only) file that must be saved to built-in flash (non-volatile storage) before rebooting. Many separate config files can be saved, but only one can be the selected startup-config. For details, see the built-in help text for the admin-exec copy and show commands.

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

## 6 Firmware Upgrade

Firmware upgrade is supported from the CLI, WebUI, and WeConfig tool. The CLI only supports FTP/TFTP upgrade but the WebUI and WeConfig tool can also upgrade via CGI upload – making them the ultimate choice if you have no FTP/TFTP server available or do not care to set one up.

### 6.1 WeOS Image

WeOS devices run from a built-in flash disk and usually comes with three partitions: primary, secondary, and boot. The latter is for the boot loader (see below) and the primary is the main WeOS image partition. Should this ever get corrupted, e.g. due to power-loss during upgrade, the device will boot using an image from the secondary (or backup) partition. This is a very appreciated, but mostly unknown, robustness feature.

```
redfox-4d-3b-20 :/#> upgrade primary <SERVER-ADDRESS> WeOS-5.27.0.pkg
```

The system must reboot when upgrading the partition image the system started on. This protects against flash corruption issues seen in earlier releases, caused by simultaneous access to the flash during programming or when starting new processes after an upgrade. Also, WeOS warns when one of the partitions has an image with invalid CRC. Attempting to upgrade the partition with the OK CRC is discouraged, upgrade the partition with the invalid CRC first.

As usual, when upgrading from an earlier release, we always recommend backing up your configuration beforehand.

**Note:** The version string listed in the output from the `show system-information` command in the CLI, or the System Details page in the WebUI, is only updated after reboot.

### 6.2 Boot Loader

The boot loader firmware has its own version numbering scheme and is CPU platform specific. Please note, unless the release notes explicitly recommends it, there is usually no need to upgrade the boot loader.

The boot loader firmware is included in the WeOS-5.27.0.pkg.

- Viper-3000 Series (Coronet): Barebox 2024.03.0-3
- RedFox-5000/7000 and Lynx-5000 Series (Dagger): Barebox 2024.03.0-3
- Lynx-3000 Series (Envoy): Barebox 2024.03.0-3
- Lynx-RB (Byron): Uboot 2024.04.0-1

```
redfox-4d-3b-20 :/#> upgrade boot <SERVER-ADDRESS> WeOS-5.27.0.pkg
```

Document

Release Notes WeOS 5.27.0

Date

December 16, 2025

Document No

224004-g0e717d2

## 7 Significant differences between WeOS 4 and WeOS 5

Some aspects of the CLI are different between WeOS 4 and WeOS 5. Here are some examples:

- Access port names have changed, e.g. Eth 1 is now eth1. Similarly, on products with M12 ports, Eth X1 is now ethX1.
- Port ranges (lists) have changed, e.g. Eth 1-8 is now eth1..eth8
- Server and Internet port settings are now usually input as ADDR:PORT
- IGMP settings have been renamed from `igmp-foo` to `multicast-foo` due to the included MLD snooping support. Hidden compatibility aliases exist to ease the transition
- Stateless NAT (NAT 1-to-1) has moved out from the firewall context
- Enabling management services per interface has moved to each specific service
- Configuration of management services have moved to a separate management sub-context
- New discovery services, in addition to LLDP, are mDNS and SSDP. The latter is for discovery on Windows systems, see also section 5
- The DHCP relay agent CLI syntax has changed considerably
- The `show running-config` command now lists an actual file, in JSON format as mentioned previously. An optional keyword now lists the first level JSON object, and more advanced keywords can also be given in `jq` syntax<sup>1</sup>. For more information, see the CLI online help text for `help running-config`

---

<sup>1</sup>For more information on `jq`, a JSON query tool, see <https://stedolan.github.io/jq/>

This page intentionally left blank.